



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-DTEC ES GT
Colour	Silver
Year of manufacture	2010
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption



Power	148 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1	
Date	2022-03-19
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-28
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	46
Total items failed	14

MOT #19	2024-04-09 13:08
MOT test number	728006906280
Result	✓ Passed
Next expiry date	2025-04-28
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #18	2024-04-06 09:16
MOT test number	752880069667
Result	✗ Failed
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 225.50.17 (5.2.3 (e))
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
Fail	Rear Anti-roll bar pin or bush excessively worn D bushes (5.3.4 (a) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm 225.50.17 (5.2.3 (e))

**MOT #17** 2023-04-29 09:00**MOT test number** 804729367664**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 225/50/17 (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Central Rear Seat belt slightly damaged (7.1.2 (b) (i))**MOT #16** 2022-05-19 14:50**MOT test number** 249224323171**Result** ✓ Passed**Advice** Central Rear Seat belt slightly damaged Two little cuts. (7.1.2 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing Slightly perished on tread. (5.2.3 (d) (ii))**MOT #15** 2021-05-14 07:59**MOT test number** 405299425190**Result** ✓ Passed**MOT #14** 2020-05-15 08:38**MOT test number** 995942366739**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #13** 2019-05-21 13:35**MOT test number** 176748327632**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #12** 2019-05-17 11:00**MOT test number** 361043634156**Result** ✗ Failed**Advice** Items removed from driver's view prior to test**Fail** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #11** 2018-05-18 13:14**MOT test number** 404167344830**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Items removed from driver's view prior to test sat/nav and airfreshner**Advice** Central Rear Seat belt cut but webbing not significantly weakened (5.2.2a)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #10** 2018-05-11 15:28**MOT test number** 204175240221**Result** ✗ Failed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Items removed from driver's view prior to test sat/nav and airfreshner**Advice** Central Rear Seat belt cut but webbing not significantly weakened (5.2.2a)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Rear Seat belt damaged sufficient to significantly weakened the webbing (5.2.2a)

**MOT #9** 2017-05-26 09:04**MOT test number** 200808064321**Result** ✓ Passed**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front registration plate deteriorated but not likely to be misread damaged (6.3.1d)**MOT #8** 2017-05-26 09:04**MOT test number** 329184297757**Result** ✗ Failed**Pass with rectification** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' sat nav/airfreshners (8.3.1e)**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Front registration plate deteriorated but not likely to be misread damaged (6.3.1d)**MOT #7** 2016-05-16 15:59**MOT test number** 318409433809**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** N/s/r light assy damaged**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

**MOT #6** 2016-05-16 09:57**MOT test number** 730149799733**Result** ✗ Failed

**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' sat nav (various) (8.3.1e)

**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

**Advice** N/s/r light assy damaged

**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure also cut to cords(225/50r17) (4.1.D.1b)

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #5** 2015-06-04 14:48**MOT test number** 569485955109**Result** ✓ Passed

**Notice** Items removed from driver's view prior to test

**MOT #4** 2015-05-18 09:50**MOT test number** 498848635186**Result** ✗ Failed

**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

**Notice** Items removed from driver's view prior to test

**MOT #3** 2014-05-12 16:53**MOT test number** 757172334199**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Service indicator on
- Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Items removed from driver's view prior to test

**MOT #2** 2013-05-17 12:51**MOT test number** 629087033165**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Items removed from driver's view prior to test

**MOT #1** 2013-05-17 12:51**MOT test number** 756517833168**Result** ✗ Failed

- Notice** Items removed from driver's view prior to test
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Notice** Under-trays fitted obscuring some underside components
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Notice** Child seat fitted not allowing full inspection of adult belt





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
28 April 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	28 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-04
Last registration	2024-04-09
Complete history	<a href="#">See info</a>



Registration #1	2010-06-04	12 mi
Registration #2	2013-05-17	43.603 mi
Registration #3	2014-05-12	50.372 mi
Registration #4	2015-05-18	57.666 mi
Registration #5	2015-06-04	57.945 mi
Registration #6	2016-05-16	65.545 mi
Registration #7	2016-05-16	65.551 mi
Registration #8	2017-05-26	72.687 mi
Registration #9	2017-05-26	72.687 mi
Registration #10	2018-05-11	80.603 mi
Registration #11	2019-05-20	88.603 mi
Registration #12	2019-05-20	88.603 mi
Registration #13	2019-05-20	88.603 mi
Registration #14	2019-05-20	88.603 mi
Registration #15	2019-05-20	88.603 mi
Registration #16	2019-05-20	88.603 mi
Registration #17	2019-05-20	88.603 mi
Registration #18	2019-05-20	88.603 mi
Registration #19	2019-05-20	88.603 mi
Registration #20	2019-05-20	88.603 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4740 mm
Wheel base	2705 mm
Kerb weight	1559 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	N22B11103670