





report date: 2024-03-29

#### General information

Make	PEUGEOT
Model	HORIZON HDI ALLURE
Colour	Silver
Year of manufacture	2013
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



report date: 2024-03-29


# Internet history

#### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-02-22
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	13
Total items failed	11

MOT #11	2024-02-23 16:44
MOT test number	759065003100
Result	✓ Passed
Next expiry date	2025-02-22

MOT #	10	2024-01-26 09:30
MOT te	st number	607153566706
Result		<b>X</b> Failed
Fail	Windscreen washer not working (3.5 (a))	
Fail	Exhaust system insecure rear back box (6.1.2 (a))	
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Offside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Exhaust has a major leak of exhaust gases center pipe broke (6.1.2 (a))	
Fail	Central Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9	2023-01-26 12:46
MOT test number	132200154552
Result	✓ Passed
MOT #8	2021-02-09 10:52
MOT test number	610364857246
Result	✓ Passed
MOT #7	2021-02-08 16:01
MOT test number	383333480706
Result	<b>×</b> Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #6		2020-06-19 11:07
MOT test	number	707432449532
Result		✓ Passed
Advice	Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT test number

Result

Advice

Offside Rear Tyre slightly damaged/cracking or perishing Side walls. (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing Side walls. (5.2.3 (d) (ii))

MOT #4

MOT test number

462242635886

Result

Advice Items removed from driver's view prior to test

MOT #3

2017-07-26 13:14

MOT test number

254011263611

Result

MOT #2

2017-07-26 13:14

MOT test number

182036799191

Result

Pass with rectification

Central Stop lamp not working high level (1.2.1b)

MOT #1

MOT test number

Fesult

Advice

Offside Rear flexy brake pipe close to exhaust (ok at time of test)

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	22 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

# Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates faste since

CarCheck.co.uk page 9/12



SD63FFR report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-11-18
Last registration	2024-02-23
Complete history	See info



Registration #1	2013-11-18	17 mi
Registration #2	2016-09-09	10.330 mi
Registration #3	2017-07-26	13.823 mi
Registration #4	2017-07-26	13.823 mi
Registration #5	2018-06-19	17.124 mi
Registration #6	2019-05-28	20.829 mi
Registration #7	2020-06-19	24.437 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		0.00 44
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	89%
Children	79%
Pedestrian	37%
Safety systems	97%
Overall rating	77%
Video	see crash video



## Dimensions & weight

Width	2118 mm
Height	1638 mm
Length	4530 mm
Wheel base	2728 mm
Kerb weight	1699 kg
Max. allowed weight	2250 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/1

Number of axles 2

**Engine number** JBER0104213