



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ALLURE COUPE CABRIOLET
Colour	Silver
Year of manufacture	2004
Top speed	120 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	166 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-02-03
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-30
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	58
Total items failed	17

MOT #23	2023-05-31 13:56
MOT test number	801342407690
Result	✓ Passed
Next expiry date	2024-05-30

MOT #22	2023-05-31 08:45
MOT test number	951863017246
Result	✗ Failed
Fail	Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #21	2021-06-28 15:32
MOT test number	324980624509
Result	✓ Passed

MOT #20	2021-06-28 10:35
MOT test number	653357877713
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #19**

2019-06-21 14:52

MOT test number

293640179193

Result

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases from front to centre joint (6.1.2 (a))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive lower part of engine and gear box damp of oil (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view chip in lower section of screen (3.2 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower wishbone both inner bushes (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #18

2019-06-21 09:45

MOT test number

278274646682

Result

✗ Failed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower wishbone both inner bushes (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Windscreen wiper blade defective both blades split on ends/ slightly smeary (3.4 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases from front to centre joint (6.1.2 (a))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view chip in lower section of screen (3.2 (a) (i))
- Advice** Park brake travel high
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn very close to limit (5.2.3 (e))
- Advice** Oil leak, but not excessive lower part of engine and gear box damp of oil (8.4.1 (a) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #17	2018-06-22 15:00
MOT test number	930741110464
Result	✓ Passed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #16	2018-06-22 11:58
MOT test number	381081908420
Result	✗ Failed
Fail	Nearside Front Side repeater incorrect colour (4.4.3 (a))
Minor	Offside Front Windscreen wiper blade defective (3.4 (b) (i))
Fail	Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #15	2017-06-26 08:36
MOT test number	856755428060
Result	✓ Passed
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #14	2016-06-27 14:57
MOT test number	183926542798
Result	✓ Passed
Advice	Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Both (2.4.G.2)
Advice	Oil leaking from engine
Advice	Front coil spring corroded both (2.4.C.1b)



MOT #13	2015-05-26 16:32
MOT test number	369906745197
Result	✓ Passed
Notice	Oil leak

MOT #12	2015-05-26 11:13
MOT test number	287026945447
Result	✗ Failed
Fail	Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Oil leak
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #11	2014-06-16 15:13
MOT test number	157397564153
Result	✓ Passed
Notice	Oil leak
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Offside wing mirror outer casing damaged
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2014-06-12 10:56**MOT test number** 657303064107**Result** ✗ Failed**Notice** Offside wing mirror outer casing damaged**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Fail** Nearside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2013-07-22 13:42**MOT test number** 615293503264**Result** ✓ Passed**MOT #8** 2012-07-11 16:29**MOT test number** 409073992171**Result** ✓ Passed**MOT #7** 2011-07-22 17:26**MOT test number** 586543401282**Result** ✓ Passed

**MOT #6** 2010-03-11 14:34**MOT test number** 564230970017**Result** ✓ Passed**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**MOT #5** 2009-03-19 14:21**MOT test number** 372938379021**Result** ✓ Passed**Notice** Oil leak**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Rear tyres cracking**Advice** Rear brake disc slightly pitted (3.5.1h)**MOT #4** 2009-03-19 14:21**MOT test number** 702968079000**Result** ✗ Failed**Notice** Oil leak**Pass with rectification** Registration plate lamp not working (1.1.5c)**Advice** Rear brake disc slightly pitted (3.5.1h)**Notice** Rear tyres cracking**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)

**MOT #3** 2008-03-25 13:19**MOT test number** 451355888074**Result** Passed**MOT #2** 2008-03-22 11:02**MOT test number** 202182888078**Result** Failed**Fail** Horn not working (1.6.2a)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Notice** Front brake pads uneven wear**Fail** Offside Registration plate lamp not working (1.1.5c)**Notice** Both front tyres worn 2mm**MOT #1** 2007-03-08 14:54**MOT test number** 302397267052**Result** Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** ** FRONT BRAKE DISCS WORN/LIPPED/CORRODED (INNER FACES) ****Notice** BOLT MISSING FROM HEAT SHIELD**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Notice** REAR TYRES PERISHING/CRACKING



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
30 May 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	30 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2004-03-27
Last registration	2023-05-31
Complete history	See info



Registration #1	2004-03-27	14 mi
Registration #2	2007-03-08	36.185 mi
Registration #3	2008-03-22	40.257 mi
Registration #4	2008-03-25	40.257 mi
Registration #5	2009-03-19	43.786 mi
Registration #6	2010-03-11	47.464 mi
Registration #7	2011-07-22	52.023 mi
Registration #8	2012-07-11	63.354 mi
Registration #9	2013-07-22	76.375 mi
Registration #10	2014-06-12	85.203 mi
Registration #11	2014-06-16	85.203 mi
Registration #12	2015-05-26	89.711 mi
Registration #13	2015-05-26	89.711 mi
Registration #14	2015-05-26	89.711 mi
Registration #15	2015-05-26	89.711 mi
Registration #16	2015-05-26	89.711 mi
Registration #17	2015-05-26	89.711 mi
Registration #18	2015-05-26	89.711 mi
Registration #19	2015-05-26	89.711 mi
Registration #20	2015-05-26	89.711 mi
Registration #21	2015-05-26	89.711 mi
Registration #22	2015-05-26	89.711 mi
Registration #23	2015-05-26	89.711 mi
Registration #24	2015-05-26	89.711 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1140 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	FX5N2427113