





## General information

Make	BMW
Model	5 SERIES 520D M SPORT TOURING
Colour	Grey
Year of manufacture	2009
Top speed	139 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	174 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G







# Internet history

Entry 5		
Date	2021-11-05	
Pictures	11	
Listing price	View report	



source: autotrader.co.uk

Entry 4	
Date	2021-10-17
Pictures	11
Listing price	View report



source: autotrader.co.uk

Entry 3	
Date	2021-08-27
Pictures	11
Listing price	View report









source: autotrader.co.uk

2021-06-24

## Pictures

Listing price

11

View report



#### source: autotrader.co.uk

Entry 1	
Date	2021-01-28
Pictures	1
Listing price	View report



source: autoonline.co.uk



# MOT history

MOT expiry date	2025-05-20
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	26
Total items failed	7

MOT #16	2024-04-23 15:46
MOT test number	350115272882
Result	✓ Passed
Next expiry date	2025-05-20
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge	e (5.2.3 (e))
Minor Offside Registration plate lamp inoperative in the case of multiple lam	nps or light sources (4.7.1 (b)
Minor Nearside Headlamp cleaning device inoperative (4.1.6 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	
<b>Minor</b> Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning inner section of lamp not working (4.2.1 (a) (i))	
Minor Offside Headlamp cleaning device inoperative (4.1.6 (a) (i))	



HG59BOV report date: 2024-03-29

MOT #15	2024-04-22 10:13	
MOT test number	270225158305	
Result	🗙 Failed	
Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))		
Minor Nearside Headlamp cleaning device inoperative (4.1.6 (a) (i))		
Fail         Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e)	))	
<b>Minor</b> Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning inner section of lamp not working (4.2.1 (a) (i))		
<b>Fail</b> Nearside Rear Road wheel fractured inner bead rim (5.2.2 (a))		
<b>Minor</b> Offside Headlamp cleaning device inoperative (4.1.6 (a) (i))		
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light (i))	sources (4.7.1 (b)	

MOT #14		2023-04-26 15:44
MOT test	number	334556965194
Result		✓ Passed
Advice	Offside Rear Brake hose slightly deteriorated perishing (1.1.12 (b) (ii))	
Advice	Nearside Rear Brake hose slightly deteriorated perishing (1.1.12 (b) (ii))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #13		2023-04-26 11:11
MOT test	number	434813388084
Result		🗙 Failed
Advice	Nearside Rear Brake hose slightly deteriorated perishing (1.1.12 (b) (ii))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Brake hose slightly deteriorated perishing (1.1.12 (b) (ii))	
<b>Fail</b> Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer side wall (5.2.3 (d) (i))		





MOT #12	2022-05-21 10:07
MOT test number	190469341434
Result	✓ Passed
MOT #11	2021-01-14 09:57
MOT test number	969416768585
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (	(3.2 (a) (i))

MOT #10	2019-12-21 10:02
MOT test number	913777119546
Result	✓ Passed
Minor Front Windscreen damaged but not adversely affect	ting driver's view (3.2 (a) (i))

МОТ #9	2018-12-29 12:32
MOT test number	566541081747
Result	✓ Passed

MOT #8	2017-09-04 11:48
MOT test number	546465461241
Result	✓ Passed

MOT #7	201	6-08-01 15:46
MOT test	number 4	72978037469
Result		🗸 Passed
Advice	Rear 2x child seats fitted	
<b>Advice</b> (1.2.1b)	Rear Upper Stop lamp has light sources not illuminating, but not more than 50% high	level
Advice	Rear Brake hose slightly deteriorated (3.6.B.4d)	



HG59BOV
report date: 2024-03-29

MOT #6	2016-08-01 10:28		
MOT test number	359514321928		
Result	🗙 Failed		
Fail         Nearside Front Front position lamp(s) not working (1.1.A.3b)			
Advice Rear 2x child seats fitted			
<b>Fail</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)			
MOT #5	2015-08-25 11:48		
MOT test number	787058652226		
Result	✓ Passed		
MOT #4	2015-08-25 09:05		
MOT test number	657407606124		
Result	× Failed		
Fail         Offside Rear fog lamp not working (1.3.2b)			
Fail         Offside Registration plate lamp not working (1.1.C.1d)			

МОТ #3	2014-08-19 11:45
MOT test number	939021734262
Result	✓ Passed
<b>Notice</b> Did not check o/s/r seatbelt as childseat	
MOT #2	2013-08-30 09:19

MOT test number	306262943287
Result	✓ Passed





MOT #1	2012-10-12 11:04
MOT test number	286236782244
Result	🗸 Passed
<b>Notice</b> Under-trays fitted obscuring some underside components	



Tax & MOT check

	√ xed		✓ MOT
Tax due: 1 May 2025		<b>Expires:</b> 20 May 2025	
Tax status			Valid until 1 May
Days left			367
MOT expiry date			20 May 2025
Full MOT history			<u>See MOT history</u>

# Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lampe
Туре	
Damage 2	AMPLE
Damage 2	E E E E
Date	S.
Category	ame
Туре	

#### Extra BMW salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

***********	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	
Current registration Plate since	
Current registration Pate since Current registration	
Carrent registration Plate since Carrent registration Plate since	8775-25-27





### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-09-30
Last registration	2024-04-23
Complete history	<u>See info</u>



Registration #1	2009-09-30	25 mi
Registration #2	2012-10-12	26.599 mi
Registration #3	2013-08-30	31.942 mi
Registration #4	2014-08-19	39.545 mi
Registration #5	2015-08-25	48.161 mi
Registration #6	2015-08-25	48.161 mi
Registration #7	2016-08-01	54.732 mi
Registration #8	2016-08-01	54.732 mi
Registration #9	2017-09-04	61.450 mi
Registration #10	2018-12-29	75.669 mi
Registration #11	2019-12-21	83.500 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		11.777 est
Registration #19		11.777 mi
Registration #20		11.317 esi
Registration #21		11.777 mi
Registration #22		11.777 est





## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1846 mm
Height	1491 mm
Length	4843 mm
Wheel base	2886 mm
Kerb weight	1695 kg
Max. allowed weight	2220 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	83597148