



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 S S40
Colour	Grey
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-01-03
Pictures	8
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-12-27
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #22	2021-01-09 11:01
MOT test number	105692500811
Result	✓ Passed
Next expiry date	2022-01-09
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #21	2019-12-24 15:01
MOT test number	744316128259
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Brake disc worn, but not excessively all four (1.1.14 (a) (i))

MOT #20	2019-12-24 15:01
MOT test number	555907771770
Result	✗ Failed
Advice	Brake disc worn, but not excessively all four (1.1.14 (a) (i))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2019-12-23 16:29

MOT test number

813735533022

Result**✗ Failed**

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Tyre worn close to legal limit/worn on edge both side (size 235.40.R 18) (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** All round brake discs back plate rusty
- Fail** Emissions not tested (8.2.1.2 (d))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both side (6.1.1 (c) (i))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Wheel alignment recommended.
- Advice** Offside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #18

2019-01-05 13:43

MOT test number

800931756168

Result**✓ Passed**

- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Slight smoke on idle

MOT #17

2018-01-10 17:54

MOT test number

389722398360

Result**✓ Passed**

**MOT #16** 2018-01-05 17:11**MOT test number** 305103635200**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort 48 vs 113 (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #15** 2016-12-22 14:22**MOT test number** 669384368339**Result** ✓ Passed**Advice** Offside Front rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside Rear slight roughness in bearing**MOT #14** 2016-01-04 16:49**MOT test number** 447845528618**Result** ✓ Passed**MOT #13** 2015-12-29 16:50**MOT test number** 195746046590**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Exhaust system not adequately supported (7.1.1)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front coil spring broken (2.4.C.1a)

**MOT #12** 2014-04-08 10:18**MOT test number** 359808094071**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)**Advice** Nearside Front Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)**MOT #11** 2013-04-09 11:38**MOT test number** 158729693006**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2013-04-08 12:59**MOT test number** 835018293034**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2012-04-03 13:52

MOT test number

236404092042

Result

✓ Passed

Notice Both front brake discs worn**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #8**

2012-04-02 16:51

MOT test number

145873492014

Result

✗ Failed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Front suspension has slight play in a pin or bush of an lower wishbone inner bearing (2.5.B.1a)**Notice** Both front brake discs worn**Fail** Nearside Front Front suspension has excessive play in a pin or bush of a lower wishbone inner bearing (2.5.B.1a)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #7**

2011-04-04 17:06

MOT test number

495304591037

Result

✓ Passed

Advice Nearside Front wheel bearing has slight play (2.5.A.3c)**Notice** N/s/f tyre has cut on outer wall but not exposing cord

**MOT #6** 2011-04-04 11:28**MOT test number** 775254291084**Result** ✗ Failed**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** N/s/f tyre has cut on outer wall but not exposing cord**MOT #5** 2010-04-06 11:51**MOT test number** 903266890052**Result** ✗ Failed**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #4** 2010-04-06 11:51**MOT test number** 774976490038**Result** ✓ Passed**MOT #3** 2009-04-09 12:01**MOT test number** 633259199092**Result** ✓ Passed**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Airconditioning pipe support bracket fractured by compressor unit.



MOT #2	2009-03-31 16:27
MOT test number	500870599058
Result	✗ Failed
Fail	Offside Rear Road wheel cracked (4.2.A.1a)
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
Notice	Airconditioning pipe support bracket fractured by compressor unit.
Advice	Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #1	2008-03-07 12:16
MOT test number	813587868042
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-20
Current registration	*****
Plate since	2019-06-20

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-03-29
Last registration	2021-01-09
Complete history	See info



Registration #1	2005-03-29	22 mi
Registration #2	2008-03-07	37.780 mi
Registration #3	2009-03-31	49.291 mi
Registration #4	2009-04-09	49.311 mi
Registration #5	2010-04-06	62.066 mi
Registration #6	2011-04-04	75.311 mi
Registration #7	2011-04-04	75.311 mi
Registration #8	2012-04-02	91.496 mi
Registration #9	2012-04-03	91.496 mi
Registration #10	2013-04-08	98.672 mi
Registration #11	2013-04-09	98.672 mi
Registration #12	2014-04-08	105.289 mi
Registration #13	2015-04-08	111.877 mi
Registration #14	2015-04-08	111.877 mi
Registration #15	2015-04-08	111.877 mi
Registration #16	2015-04-08	111.877 mi
Registration #17	2015-04-08	111.877 mi
Registration #18	2015-04-08	111.877 mi
Registration #19	2015-04-08	111.877 mi
Registration #20	2015-04-08	111.877 mi
Registration #21	2015-04-08	111.877 mi
Registration #22	2015-04-08	111.877 mi
Registration #23	2015-04-08	111.877 mi
Registration #24	2015-04-08	111.877 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1376 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	12922