





report date: 2024-03-28

## General information

Make	MINI
Model	ONE
Colour	White
Year of manufacture	2016
Top speed	121 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	101 BHP
Max. torque	180 Nm at 1.400 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	70.6 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/12



## Internet history

## Entry 1


Date 2022-04-04

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



PY16LCG

report date: 2024-03-28

# MOT history

MOT expiry date	2025-03-24
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	12
Total items failed	13

MOT #9	2024-03-09 10:37
MOT test number	639709698834
Result	✓ Passed
Next expiry date	2025-03-24

MOT #	8	2024-03-07 15:16
MOT te	est number	710403968161
Result		<b>X</b> Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail	Offside Front Headlamp aim too high (4.1.2 (a))	
Fail	Nearside Front Headlamp aim too high (4.1.2 (a))	
Fail	Headlamp levelling device inoperative (4.1.5 (a))	

MOT #7		2023-02-25 10:36
MOT test	number	601922162225
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



**PY16LCG** 

report date: 2024-03-28

MOT #	6	2022-03-25 18:19
MOT to	est number	227056668408
Result		✓ Passed
MOT #	5	2022-03-22 11:36
MOT to	est number	935131779557
Result		<b>×</b> Failed
Fail	Nearside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Emissions not tested (8.2.1.2 (d))	
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
Fail	Offside Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))	
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #4		2021-01-29 15:33
MOT test	number	972501110080
Result		<b>✓</b> Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing on outer edge (5.2.3 (e))		
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 4/12



PY16LCG

report date: 2024-03-28

MOT #3 2021-01-28 10:03

**MOT test number** 423798890147

**Result** X Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge near limit & worn smooth on outer edge (5.2.3 (e))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge near limit & worn smooth on outer edge (5.2.3 (e))

Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-07-30 12:41

MOT test number 644625746002

Result \( \sqrt{Passed} \)

MOT #1 2019-07-30 10:44

MOT test number 841430896643

Result × Failed

**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	24 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
MARKET STATE OF THE STATE OF TH	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-07-30
Last registration	2024-03-09
Complete history	See info



Registration #1	2016-07-30	15 mi
Registration #2	2019-07-30	64.697 mi
Registration #3	2019-07-30	64.697 mi
Registration #4	2021-01-28	89.297 mi
Registration #5	2021-01-29	89.297 mi
Registration #6	2022-03-22	100.424 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 est
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3821 mm
Wheel base	2495 mm
Kerb weight	1090 kg
Max. allowed weight	1570 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberF515H297