



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE
Colour	Black
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	6.6 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-08-15
Pictures	37
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #14 2023-08-10 09:36

MOT test number 117826765360

Result ✓ Passed

Next expiry date 2024-08-12

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2022-08-08 14:08

MOT test number 812160002798

Result ✓ Passed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #12 2022-08-08 14:08

MOT test number 738039635088

Result ✗ Failed

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

MOT #11 2021-08-13 15:59

MOT test number 467461231370

Result ✓ Passed

**MOT #10** 2021-03-05 16:13**MOT test number** 832500481232**Result** ✓ Passed**MOT #9** 2021-03-05 09:17**MOT test number** 834078396886**Result** ✗ Failed

**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2020-03-12 09:10**MOT test number** 202810094291**Result** ✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Front Inner cv boot perishing

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-03-13 15:25**MOT test number** 177990679027**Result** ✓ Passed

**MOT #6** 2019-03-13 08:46**MOT test number** 400372282365**Result** ✗ Failed

**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**Fail** Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #5** 2018-03-22 14:48**MOT test number** 429340769239**Result** ✓ Passed**MOT #4** 2018-03-21 08:43**MOT test number** 910869367960**Result** ✗ Failed

**Fail** Nearside Front Inner Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**Fail** Offside Front Inner Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #3** 2017-03-10 08:58**MOT test number** 339045102876**Result** ✓ Passed

**Advice** Both front tyres worn in inner/outer edge

**Advice** Both front wishbone arm rear bushes worn

**MOT #2** 2016-03-23 11:44**MOT test number** 980361635667**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-03-04 10:26
MOT test number	758653565097
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
12 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	12 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-24
Last registration	2023-08-10
Complete history	<a href="#">See info</a>



Registration #1	2012-03-24	19 mi
Registration #2	2015-03-04	44.647 mi
Registration #3	2016-03-23	54.645 mi
Registration #4	2017-03-10	63.528 mi
Registration #5	2018-03-21	73.354 mi
Registration #6	2018-03-22	73.414 mi
Registration #7	2019-03-13	81.789 mi
Registration #8	2019-03-13	81.789 mi
Registration #9	2019-03-13	81.789 mi
Registration #10	2019-03-13	81.789 mi
Registration #11	2019-03-13	81.789 mi
Registration #12	2019-03-13	81.789 mi
Registration #13	2019-03-13	81.789 mi
Registration #14	2019-03-13	81.789 mi
Registration #15	2019-03-13	81.789 mi
Registration #16	2019-03-13	81.789 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1433 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	2041867