



report date: 2024-03-28

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Blue
Year of manufacture	2011
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-25
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	24
Total items failed	7

MOT #14	2023-08-21 09:09
MOT test number	191223185480
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Offside Front Play in steering rack inner joint(s)

MOT #13	2023-08-21 09:09
MOT test number	381409449190
Result	✗ Failed
Pass with rectification	Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))
Pass with rectification	Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Advice	Offside Front Play in steering rack inner joint(s)
Pass with rectification	Nearside Front Headlamp aim too high (4.1.2 (a))

MOT #12	2022-08-17 13:07
MOT test number	276288934298
Result	✓ Passed
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #11** 2021-08-31 09:51**MOT test number** 888140814800**Result** ✓ Passed**MOT #10** 2021-03-29 09:05**MOT test number** 125567246512**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2021-03-29 09:05**MOT test number** 576860789536**Result** ✗ Failed**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #8** 2020-03-12 11:13**MOT test number** 423683359050**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7**

2019-03-06 11:50

MOT test number

599505812695

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner and outer treads (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge wearing on inner and outer treads (5.2.3 (e))

Advice

Rear Child Seat fitted not allowing full inspection of adult belt x 2 / n/s/r and o/s/r

MOT #6

2019-03-06 11:50

MOT test number

406086679411

Result

✗ Failed

Advice

Rear Child Seat fitted not allowing full inspection of adult belt x 2 / n/s/r and o/s/r

Pass with rectification

Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge wearing on inner and outer treads (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge wearing on inner and outer treads (5.2.3 (e))

MOT #5

2018-03-12 10:04

MOT test number

453520110797

Result

✓ Passed

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)

Advice

Rear Child Seat fitted not allowing full inspection of adult belt nearside and offside

Advice

Under body shields fitted obscuring some components

**MOT #4** 2017-03-21 14:04**MOT test number** 638907426922**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2016-03-18 14:03**MOT test number** 531383162363**Result** ✓ Passed**MOT #2** 2015-03-12 11:24**MOT test number** 677911575079**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2014-03-15 15:40**MOT test number** 157934274059**Result** ✓ Passed**Notice** Both sides front tyres worn on outside edges



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
30 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	EX11BTV
Plate since	2019-09-28
Current registration	EX11BTV
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-29
Last registration	2023-08-21
Complete history	See info



Registration #1	2011-03-29	23 mi
Registration #2	2014-03-15	23.034 mi
Registration #3	2015-03-12	31.365 mi
Registration #4	2016-03-18	39.312 mi
Registration #5	2017-03-21	44.031 mi
Registration #6	2018-03-12	49.660 mi
Registration #7	2019-03-06	58.080 mi
Registration #8	2019-03-06	58.080 mi
Registration #9	2019-03-06	58.080 mi
Registration #10	2019-03-06	58.080 mi
Registration #11	2019-03-06	58.080 mi
Registration #12	2019-03-06	58.080 mi
Registration #13	2019-03-06	58.080 mi
Registration #14	2019-03-06	58.080 mi
Registration #15	2019-03-06	58.080 mi
Registration #16	2019-03-06	58.080 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	76%
Children	79%
Pedestrian	43%
Safety systems	71%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R210287355