



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO GBT
Colour	White
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 2


Date	2022-05-08
Pictures	32
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-26
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-27
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	22
Total items failed	12

MOT #13	2023-07-28 11:38
MOT test number	433264972271
Result	✓ Passed
Next expiry date	2024-07-27

MOT #12	2022-05-03 10:45
MOT test number	967655019653
Result	✓ Passed

MOT #11	2022-03-01 12:11
MOT test number	192235577836
Result	✗ Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2020-10-30 08:24
MOT test number	724187498253
Result	✓ Passed

- Advice** Exhaust corroded
- Advice** Engine starting to burn oil (light blue smoke)
- Advice** Nearside mirror damaged
- Advice** Engine oil level very low

**MOT #9**

2020-10-21 15:08

MOT test number

568618182742

Result**✗ Failed****Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Exhaust corroded**Advice** Engine starting to burn oil (light blue smoke)**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps All not working (4.7.1 (b) (ii))**Advice** Nearside mirror damaged**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Engine oil level very low**Fail** Nearside Reversing lamp inoperative Missing (4.6.1 (a))**MOT #8**

2019-10-26 13:27

MOT test number

345601433115

Result**✓ Passed****Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7** 2019-10-26 13:27**MOT test number** 134231746429**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Front Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-10-12 11:05**MOT test number** 938194791698**Result** ✓ Passed**Advice** Offside Front Indicator lense broken but still has a amber light output**MOT #5** 2018-10-10 15:05**MOT test number** 645278271756**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Non obligatory mirror damaged Cracked**Advice** Offside Front Indicator lense broken but still has a amber light output**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))



MOT #4	2017-10-30 12:02
---------------	------------------

MOT test number	673134438571
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	N/s/f door mirror deteriorated.
---------------	---------------------------------

MOT #3	2016-09-23 09:45
---------------	------------------

MOT test number	781190911627
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2016-09-23 09:45
---------------	------------------

MOT test number	759840357053
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Rear Stop lamp not working (1.2.1b)
--------------------------------	--

MOT #1	2015-10-29 15:54
---------------	------------------

MOT test number	436344153902
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
27 July 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-12-27
Last registration	2023-07-28
Complete history	See info



Registration #1	2012-12-27	9 mi
Registration #2	2015-10-29	46.984 mi
Registration #3	2016-09-23	54.953 mi
Registration #4	2016-09-23	54.953 mi
Registration #5	2017-10-30	62.176 mi
Registration #6	2018-10-10	68.669 mi
Registration #7	2018-10-12	68.700 mi
Registration #8	2019-10-26	74.457 mi
Registration #9	2019-10-26	74.457 mi
Registration #10	2019-10-26	74.457 mi
Registration #11	2019-10-26	74.457 mi
Registration #12	2019-10-26	74.457 mi
Registration #13	2019-10-26	74.457 mi
Registration #14	2019-10-26	74.457 mi
Registration #15	2019-10-26	74.457 mi
Registration #16	2019-10-26	74.457 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number	0091898
---------------	---------