



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Black
Year of manufacture	2010
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-02-08
Pictures	9
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-02-21
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	19
Total items failed	9

MOT #18	2024-02-03 12:28
MOT test number	475183433743
Result	✓ Passed
Next expiry date	2025-02-21
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement most rear (5.3.4 (a) (i))

MOT #17	2024-02-03 10:33
MOT test number	982193132325
Result	✗ Failed
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Exhaust has a major leak of exhaust gases back box (6.1.2 (a))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement most rear (5.3.4 (a) (i))
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #16	2023-02-11 10:11
MOT test number	680021369458
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #15**

2023-01-28 11:21

**MOT test number**

637592887650

**Result**

✗ Failed

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Rear Exhaust system insecure box (6.1.2 (a))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush starting to split (5.3.4 (a) (i))**MOT #14**

2022-02-22 15:40

**MOT test number**

982385343957

**Result**

✓ Passed

**MOT #13**

2021-06-21 12:29

**MOT test number**

512606995984

**Result**

✓ Passed

**MOT #12**

2020-06-10 13:51

**MOT test number**

523071350653

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11**

2020-06-10 08:59

**MOT test number**

803873049389

**Result****✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #10**

2019-06-17 07:51

**MOT test number**

270911982869

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2019-06-17 07:51

**MOT test number**

601742808884

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2018-06-20 13:12

**MOT test number**

551570059432

**Result****✓ Passed**



<b>MOT #7</b>	2017-06-15 08:09
---------------	------------------

<b>MOT test number</b>	653966728538
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2016-06-21 07:55
---------------	------------------

<b>MOT test number</b>	231492250363
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2016-06-21 07:55
---------------	------------------

<b>MOT test number</b>	790832960464
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Nearside Stop lamp not working (1.2.1b)
--------------------------------	---

<b>MOT #4</b>	2015-06-16 13:53
---------------	------------------

<b>MOT test number</b>	398047465174
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2015-06-16 09:28
---------------	------------------

<b>MOT test number</b>	397197365123
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2014-06-02 12:04
---------------	------------------

<b>MOT test number</b>	337443054122
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2013-06-03 09:06
---------------	------------------

<b>MOT test number</b>	856134353116
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
21 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	21 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>YS10KGX</b>
Plate since	2019-03-29
Current registration	 <b>YS10KGX</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-06-25
Last registration	2024-02-03
Complete history	<a href="#">See info</a>



Registration #1	2010-06-25	6 mi
Registration #2	2013-06-03	10.773 mi
Registration #3	2014-06-02	15.047 mi
Registration #4	2015-06-16	19.153 mi
Registration #5	2015-06-16	19.153 mi
Registration #6	2016-06-21	23.269 mi
Registration #7	2016-06-21	23.269 mi
Registration #8	2017-06-15	27.358 mi
Registration #9	2018-06-20	31.066 mi
Registration #10	2019-06-17	34.695 mi
Registration #11	2020-06-20	38.324 mi
Registration #12	2021-06-20	41.953 mi
Registration #13	2022-06-20	45.582 mi
Registration #14	2023-06-20	49.211 mi
Registration #15	2024-02-03	52.840 mi
Registration #16	2024-02-03	52.840 mi
Registration #17	2024-02-03	52.840 mi
Registration #18	2024-02-03	52.840 mi
Registration #19	2024-02-03	52.840 mi
Registration #20	2024-02-03	52.840 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 058721