



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Silver
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





MOT history

MOT expiry date	2024-11-17
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	21
Total items failed	3

MOT #15	2023-11-09 12:56
MOT test number	324957615152
Result	✓ Passed
Next expiry date	2024-11-17
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14	2022-11-18 13:32
MOT test number	363002422622
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Outer Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #13**

2022-11-16 13:52

MOT test number

352479331755

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Outer Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Outer Side repeater not working (4.4.1 (a) (ii))**MOT #12**

2021-11-08 13:38

MOT test number

660098997938

Result

✓ Passed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #11**

2020-10-24 15:46

MOT test number

592620911731

Result

✓ Passed

Advice Engine cover and undertrays**Advice** Brake disc worn, pitted or scored, but not seriously weakened Front and rear (1.1.14 (a) (ii))**Advice** Tyre worn close to legal limit/worn on edge Both front 1.6mm (5.2.3 (e))

**MOT #10** 2019-05-16 10:36**MOT test number** 357146066116**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-05-11 10:23**MOT test number** 608292218976**Result** ✓ Passed**MOT #8** 2018-05-08 15:42**MOT test number** 630062607664**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #7** 2017-05-27 10:30**MOT test number** 287531898089**Result** ✓ Passed**MOT #6** 2016-05-31 08:58**MOT test number** 778220044118**Result** ✓ Passed



MOT #5	2015-05-29 14:01
MOT test number	138489645101
Result	✓ Passed
MOT #4	2014-06-23 09:55
MOT test number	896674874104
Result	✓ Passed
MOT #3	2013-08-13 09:34
MOT test number	725835923235
Result	✓ Passed
MOT #2	2012-08-13 10:39
MOT test number	577116522219
Result	✓ Passed
MOT #1	2011-08-26 12:25
MOT test number	155838531283
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
17 November 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	17 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-06-29
Current registration	 XXXXXX
Plate since	2020-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-01
Last registration	2023-11-09
Complete history	See info



Registration #1	2008-03-01	27 mi
Registration #2	2011-08-26	45.629 mi
Registration #3	2012-08-13	59.616 mi
Registration #4	2013-08-13	70.708 mi
Registration #5	2014-06-23	71.346 mi
Registration #6	2015-05-29	86.322 mi
Registration #7	2016-05-31	100.741 mi
Registration #8	2017-05-27	117.839 mi
Registration #9	2018-05-29	135.277 mi
Registration #10	2019-05-29	153.277 mi
Registration #11	2020-05-29	171.277 mi
Registration #12	2021-05-29	189.277 mi
Registration #13	2022-05-29	207.277 mi
Registration #14	2023-05-29	225.277 mi
Registration #15	2024-05-29	243.277 mi
Registration #16	2025-05-29	261.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 056163