



PEUGEOT




report date: 2024-03-28

General information

Make	PEUGEOT
Model	RCZ HDI GT
Colour	Blue
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



Internet history

Entry 2


Date	2021-12-03
Pictures	45
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-02
Pictures	50
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-21
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	23
Total items failed	7

MOT #16	2024-01-22 14:21
MOT test number	541308365597
Result	✓ Passed
Next expiry date	2025-01-21

MOT #15	2024-01-22 14:21
MOT test number	713802987085
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too high (4.1.2 (a))

MOT #14	2022-08-22 09:05
MOT test number	791441153793
Result	✓ Passed
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13	2021-08-11 16:51
MOT test number	119780580720
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm Also Perished (5.2.3 (e))
Advice	Nearside Non obligatory mirror damaged



MOT #12	2021-08-11 15:21
MOT test number	909145147792
Result	✗ Failed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm Also Perished (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge 2mm Also Worn Inner Shoulder (5.2.3 (e))
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Nearside Non obligatory mirror damaged

MOT #11	2020-08-06 11:44
MOT test number	187585116329
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2019-08-06 14:40
MOT test number	483257771941
Result	✓ Passed

MOT #9	2018-08-18 12:00
MOT test number	675127046660
Result	✓ Passed



MOT #8 2018-08-17 15:42

MOT test number 812293076200

Result ✗ Failed

- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (i))
- Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #7 2017-08-23 15:33

MOT test number 685282805682

Result ✓ Passed

- Advice** Nearside wing mirror damaged

MOT #6 2017-08-23 09:05

MOT test number 527544724866

Result ✗ Failed

- Advice** Nearside wing mirror damaged
- Fail** Nearside Side repeater has a product on the lens so it is not visible from a reasonable distance (1.4.A.2e)

MOT #5 2016-10-19 15:55

MOT test number 880535916937

Result ✓ Passed

- Advice** N/s/f wing mirror insecure, severely affecting the rear view.
- Advice** Front tyres have severe tears on outer sidewalls.



MOT #4 2015-10-07 16:43

MOT test number 142481473987

Result ✓ Passed

- Advice** N/s/f wing mirror insecure, seriously affecting the rear veiw.
- Advice** N/s/f tyre has slight tears and a slight cut on outer sidewall.
- Advice** N/s/r tyre has a nail.

MOT #3 2014-09-15 10:12

MOT test number 268168854299

Result ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #2 2013-09-10 16:49

MOT test number 945553053221

Result ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2013-09-10 11:09

MOT test number 656073253229

Result ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** O/s/r tyre starting to go out of shape



Tax & MOT check

✓
Taxed

Tax due:
1 February 2025

✓
MOT

Expires:
21 January 2025

Tax status	Valid until 1 February
-------------------	------------------------

Days left	278
------------------	-----

MOT expiry date	21 January 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2024-03-28
Current registration	XXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-09-23
Last registration	2024-01-22
Complete history	See info



Registration #1	2010-09-23	6 mi
Registration #2	2013-09-10	26.944 mi
Registration #3	2013-09-10	26.944 mi
Registration #4	2014-09-15	35.838 mi
Registration #5	2015-10-07	41.710 mi
Registration #6	2016-10-19	46.059 mi
Registration #7	2017-08-23	49.583 mi
Registration #8	2017-08-23	49.583 mi
Registration #9	2018-08-17	52.572 mi
Registration #10	2018-08-18	52.575 mi
Registration #11	2019-01-22	55.277 mi
Registration #12	2019-01-22	55.277 mi
Registration #13	2019-01-22	55.277 mi
Registration #14	2019-01-22	55.277 mi
Registration #15	2019-01-22	55.277 mi
Registration #16	2019-01-22	55.277 mi
Registration #17	2019-01-22	55.277 mi
Registration #18	2019-01-22	55.277 mi
Registration #19	2019-01-22	55.277 mi

[More info >](#)



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1445 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2

Engine number

DYWS4033973