





report date: 2024-03-29

### General information

Make	MERCEDES
Model	CLK CLK320 SPORT
Colour	Blue
Year of manufacture	1999
Top speed	147 mph
0 - 60 mph	7.4 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	215 BHP
Max. torque	310 Nm at 3.000 rpm
Engine capacity	3.199 сс
Cylinders	6
Fuel type	Petrol
Consumption city	18.0 mpg
• • • • • • • • • • • • • • • • • • • •	



CarCheck.co.uk page 1/14



report date: 2024-03-29

## Internet history

## Entry 2

Date 2021-08-12

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-08-10
Pictures	8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history	
MOT expiry date	2024-08-17
MOT pass rate	90 %
MOT passed	19

Failed MOT tests 2

Total advice items 30

Total items failed 2

MOT #21	2023-08-17 10:24
MOT test number	112932550181
Result	✓ Passed
Next expiry date	2024-08-17

 MOT #20
 2022-08-17 13:46

 MOT test number
 818051434668

 Result
 ✓ Passed

MOT #19

MOT test number

397449519649

Result

✓ Passed

MOT #18 2021-02-05 13:39

**MOT test number** 927181291554

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** General rust on under body

CarCheck.co.uk page 3/14



report date: 2024-03-29

**MOT #17** 2021-02-03 13:17 206485305036 **MOT** test number Result × Failed Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b)) Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice General rust on under body **Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #16** 2020-01-10 13:40 **MOT** test number 948960912255 Result Passed **Advice** Exhaust system corroded Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii)) Underside of vehicle has slight surface corrosion Advice Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2019-01-28 16:34
MOT test number	703738582427
Result	✓ Passed
Advice Nearside Front Tyre wearing low on outer edge.	
Advice Front registration plate damaged.	
Advice Both rear coil springs corroded.	

CarCheck.co.uk page 4/14



report date: 2024-03-29

 MOT #14
 2018-01-16 10:55

 MOT test number
 459265849453

**Result** ✓ Passed

MOT #13 2017-01-26 09:54

**MOT test number** 725449302637

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside front and nearside rear tyres worn on edges

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2016-01-19 12:04

**MOT test number** 928408680430

Result \( \sqrt{Passed} \)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2015-01-14 10:35

MOT test number 668584915002

**Advice** Steering damper slight oil seepage (2.2.C.1f)

MOT #10 2014-01-13 11:50

**MOT test number** 596133714087

**Result** ✓ Passed

Advice Steering damper slight oil seepage (2.2.C.1f)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #9		2013-01-25 09:48
MOT test	number	546535123011
Result		✓ Passed
Advice	Offside Side repeater slightly discoloured (1.4.A.2f)	
Notice	Final drive oil leak	
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Notice	Front number plate slightly damaged	

MOT #8	2012-01-16 10:20
MOT test number	819626812061
Result	✓ Passed
MOT #7	2011-01-28 12:45
MOT test number	595868321036
Result	✓ Passed
MOT #6	2010-01-04 14:07
MOT test number	401804600085
Result	✓ Passed
Advice Offside Rear Brake hose slightly deteriorated (3.6.B.4d)	

MOT #5	2009-01-14 15:27
MOT test number	584604119040
Result	<b>✓</b> Passed
MOT #4	2008-01-16 12:20
MOT test number	120486918474
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT test number

Result

MOT test number

Result

MOT #2

MOT test number

MOT test number

A43123427071

Result

Pass with rectification

Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #1

MOT test number

904444826025

Result

Advice Front Steering damper slight oil seepage (2.2.C.1f)

Notice Slight deterioration in offside rear brake disc

CarCheck.co.uk page 7/14



report date: 2024-03-29





Days left 215

MOT expiry date 17 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 8/14




report date: 2024-03-29

### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

More info >

## Owner history

*		
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.		
*********		
***************************************		
*********		
************		
	More info >	
Plate changes		
See in this check if this MERCEDES had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK UK	
Plate since		

CarCheck.co.uk page 11/14



report date: 2024-03-29

### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	1999-02-16
Last registration	2023-08-17
Complete history	See info



Registration #1	1999-02-16	26 mi
Registration #2	2006-01-24	34.934 mi
Registration #3	2007-01-23	39.835 mi
Registration #4	2008-01-16	43.057 mi
Registration #5	2009-01-14	46.005 mi
Registration #6	2010-01-04	48.851 mi
Registration #7	2011-01-28	51.510 mi
Registration #8	2012-01-16	53.877 mi
Registration #9	2013-01-25	56.117 mi
Registration #10	2014-01-13	58.308 mi
Registration #11	2015-01-14	60.088 mi
Registration #12	2016-01-19	61.671 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

		_		
- I ) Im	ension	c l	WAIG	nt.
וווט	CHSIUH	3 W	weiu	III.

Width	1722 mm
Height	1345 mm
Length	4567 mm
Kerb weight	1420 kg

## Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11294030361564

CarCheck.co.uk page 14/14