



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 HDI SPORT
Colour	Red
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	12.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-05
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-09
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	84
Total items failed	30

MOT #24	2023-08-03 10:34
MOT test number	499099494508
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Heat Shield Insecure

**MOT #23**

2023-07-31 13:41

MOT test number

958590389789

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear Heat Shield Insecure
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Inner Steering linkage ball joint has excessive play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect & Dim (4.1.2 (c))
- Fail** Nearside Front Inner Steering linkage ball joint has excessive play (2.1.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22**

2022-08-08 10:57

MOT test number

748199857392

Result

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #21**

2022-07-29 15:10

MOT test number

857513899872

Result**✗ Failed**

- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair grabbing (1.2.1 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Rear Service brake excessively fluctuating (1.2.1 (e))

MOT #20

2021-08-10 12:00

MOT test number

633034175127

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Tyre is perished (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Also tyre is perished (5.2.3 (e))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #19**

2020-11-06 12:26

MOT test number

293743863355

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #18

2020-10-27 12:38

MOT test number

804081134119

Result

✗ Failed

Fail

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail

Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength front subframe mounting (5.3.6 (a) (i))

Fail

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

MOT #17

2019-10-22 14:26

MOT test number

793935033390

Result

✓ Passed

**MOT #16**

2019-10-22 11:12

MOT test number

260606406684

Result

✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #15**

2018-11-02 14:59

MOT test number

332108626157

Result

✓ Passed

Advice Front Play in steering rack inner joint(s)**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #14**

2018-11-02 12:53

MOT test number

244102081529

Result

✗ Failed

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Front Play in steering rack inner joint(s)**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #13**

2017-11-03 15:32

MOT test number

897098529850

Result

✓ Passed

Advice Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Play in steering rack inner joint(s) both nearside and offside

**MOT #12**

2017-11-03 11:37

MOT test number

288456013940

Result**✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Play in steering rack inner joint(s) both nearside and offside**MOT #11**

2016-11-11 12:14

MOT test number

137214813712

Result**✓ Passed****Advice** Play in steering rack inner joint(s)**MOT #10**

2016-11-04 14:46

MOT test number

360256017121

Result**✗ Failed****Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Play in steering rack inner joint(s)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Nail in tyre**Advice** Offside Front slight binding brake**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #9** 2015-11-06 13:02**MOT test number** 335097312290**Result** ✓ Passed**Advice** Nearside rear tyre close to wear indicators**Advice** Slight play in rack ends**MOT #8** 2015-11-06 13:02**MOT test number** 173517035046**Result** ✗ Failed**Advice** Nearside rear tyre close to wear indicators**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Slight play in rack ends**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #7** 2014-11-11 14:16**MOT test number** 767865614358**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Play in steering rack inner joint(s)**Notice** Under-trays fitted obscuring some underside components**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Passenger seat(s) missing at time of test

**MOT #6** 2014-11-11 14:16**MOT test number** 797765614389**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** Under-trays fitted obscuring some underside components**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Passenger seat(s) missing at time of test**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2013-11-06 09:40**MOT test number** 105120413326**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Notice** Play in steering rack inner joint(s)**Notice** Slight binding on rear brakes**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #4** 2012-11-12 11:32**MOT test number** 547097812342**Result** ✓ Passed

- Notice** Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Passenger seat(s) missing at time of test
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** BOTH front tyres wearing on edges
- Notice** Under-trays fitted obscuring some underside components

MOT #3 2011-11-14 15:55**MOT test number** 156928711341**Result** ✓ Passed**MOT #2** 2011-04-12 13:36**MOT test number** 577442101100**Result** ✓ Passed**MOT #1** 2011-02-15 13:50**MOT test number** 385636341014**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
9 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-03-25
Last registration	2023-08-03
Complete history	See info



Registration #1	2008-03-25	23 mi
Registration #2	2011-02-15	19.266 mi
Registration #3	2011-04-12	20.397 mi
Registration #4	2011-11-14	24.973 mi
Registration #5	2012-11-12	33.846 mi
Registration #6	2013-11-06	42.861 mi
Registration #7	2014-11-11	51.163 mi
Registration #8	2015-11-06	59.714 mi
Registration #9	2015-11-06	59.714 mi
Registration #10	2016-11-04	67.919 mi
Registration #11	2016-11-11	68.034 mi
Registration #12	2017-11-03	76.094 mi
Registration #13	2017-11-03	76.094 mi
Registration #14	2018-11-03	84.154 mi
Registration #15	2018-11-03	84.154 mi
Registration #16	2019-11-03	92.214 mi
Registration #17	2019-11-03	92.214 mi
Registration #18	2020-11-03	100.274 mi
Registration #19	2020-11-03	100.274 mi
Registration #20	2021-11-03	108.334 mi
Registration #21	2021-11-03	108.334 mi
Registration #22	2022-11-03	116.394 mi
Registration #23	2022-11-03	116.394 mi
Registration #24	2023-11-03	124.454 mi
Registration #25	2023-11-03	124.454 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1821 mm
Height	1519 mm
Length	4276 mm
Wheel base	2608 mm
Kerb weight	1412 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	JBAJ3104665