



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Red
Year of manufacture	2010
Top speed	93 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-12-05
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-05
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	54
Total items failed	8

MOT #17 2023-08-18 05:33

MOT test number 285823287861

Result ✓ Passed

Next expiry date 2024-09-05

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Brake pipe corroded, covered in grease or other material both rears (1.1.11 (c))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #16 2022-09-06 10:21

MOT test number 761245640094

Result ✓ Passed

MOT #15 2022-02-28 11:09

MOT test number 271953375367

Result ✓ Passed

**MOT #14**

2021-09-07 14:51

MOT test number

865928793038

Result

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

MOT #13

2021-09-06 16:05

MOT test number

357793156839

Result

✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Brake performance not tested front to rear (1.2.1 (g))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #12**

2020-09-08 15:54

MOT test number

392780106408

Result

✓ Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material too rear (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material too rear (1.1.11 (c))**Advice** Both rear coil springs corroded**MOT #11**

2020-09-08 10:58

MOT test number

389922644450

Result

✗ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Advice** Both rear coil springs corroded**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material too rear (1.1.11 (c))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material too rear (1.1.11 (c))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #10** 2019-06-10 14:37**MOT test number** 508877088456**Result** ✓ Passed

Advice Exhaust has a minor leak of exhaust gases front hanger corroded,centre pipe slightly leaking (6.1.2 (a))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9 2019-06-10 14:37**MOT test number** 440559283729**Result** ✗ Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Exhaust has a minor leak of exhaust gases front hanger corroded,centre pipe slightly leaking (6.1.2 (a))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8 2018-06-11 13:48**MOT test number** 366410480510**Result** ✓ Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material too rear (1.1.11 (c))

Advice Wipers deteriorated

**MOT #7**

2018-06-11 09:48

MOT test number

874368477503

Result**✗ Failed****Advice**

Wipers deteriorated

Advice

Nearside Front Brake pipe corroded, covered in grease or other material too rear (1.1.11 (c))

Advice

Centre heat shields loose

Fail

Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6

2017-06-13 14:36

MOT test number

989236513233

Result**✓ Passed****Advice**

Nearside Brake pipe slightly corroded main (3.6.B.2c)

Advice

Offside Brake pipe slightly corroded main (3.6.B.2c)

MOT #5

2017-06-13 13:04

MOT test number

426965647771

Result**✗ Failed****Fail**

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Outer Brake pad(s) wearing thin (3.5.1g)

Advice

Offside Brake pipe slightly corroded main (3.6.B.2c)

Fail

Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Brake pipe slightly corroded main (3.6.B.2c)



MOT #4	2016-06-06 08:55
---------------	------------------

MOT test number	596745125381
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-06-08 10:25
---------------	------------------

MOT test number	398259355157
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-05-30 14:22
---------------	------------------

MOT test number	959220654192
------------------------	--------------

Result	✓ Passed
---------------	----------

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1	2013-06-15 10:28
---------------	------------------

MOT test number	648286163143
------------------------	--------------

Result	✓ Passed
---------------	----------

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-06-09
Last registration	2023-08-18
Complete history	See info



Registration #1	2010-06-09	22 mi
Registration #2	2013-06-15	31.630 mi
Registration #3	2014-05-30	41.571 mi
Registration #4	2015-06-08	50.567 mi
Registration #5	2016-06-06	61.627 mi
Registration #6	2017-06-13	72.084 mi
Registration #7	2017-06-13	72.084 mi
Registration #8	2018-06-11	77.807 mi
Registration #9	2018-06-11	77.807 mi
Registration #10	2019-06-10	86.037 mi
Registration #11	2019-06-10	95.277 mi
Registration #12	2019-06-10	104.517 mi
Registration #13	2019-06-10	113.757 mi
Registration #14	2019-06-10	123.000 mi
Registration #15	2019-06-10	132.243 mi
Registration #16	2019-06-10	141.486 mi
Registration #17	2019-06-10	150.729 mi
Registration #18	2019-06-10	159.972 mi
Registration #19	2019-06-10	169.215 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	1KR0998678
---------------	------------