






General information

Make	FIAT
Model	PUNTO EASY PLUS
Colour	Red
Year of manufacture	2016
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	127 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E







Internet history

Entry 1	
Date	2022-01-30
Pictures	16
Listing price	View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-17
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	13
Total items failed	11

MOT #9		2023-05-02 09:32
MOT test	number	254145455164
Result		🗸 Passed
Next expi	ry date	2024-05-17
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Exhaust has a minor leak of exhaust gases Front flexy (6.1.2 (a))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #8	2022-05-18 12:52
MOT test	number 470323145515
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases small blow from front flexi (6.1.2 (a))
Advice	Front Brake disc worn, but not excessively front brake discs worn and lipped $(1.1.14 (a) (i))$

MOT #7	2022-05-16 13:05	
MOT test number	750129579005	
Result	🗙 Failed	
Fail Windscreen washer not working (3.5 (a))		
Advice Front Exhaust has a minor leak of exhaust gases small blow from front flexi (6.1.2 (a))		
Advice Front Brake disc worn, but not excessively front brake discs worn and lipped (1.1.14 (a) (i))		





MOT #	5	2021-12-01 17:15
MOT te	st number	320310555026
Result		🗙 Failed
Fail	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail	Nearside Front Brake disc significantly and obviously worn $(1.1.14$ (a) (i))	
Fail	Exhaust has a major leak of exhaust gases (6.1.2 (a))	

MOT #5	2021-01-19 11:57
MOT test number	188046658446
Result	✓ Passed

MOT #4	4	2021-01-19 09:03
MOT te	est number	480556730631
Result		× Failed
Fail	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #3		2020-01-10 10:46
MOT test	number	363641814208
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #2		2020-01-10 10:46
MOT test number		433815916505
Result		🗙 Failed
Advice Nearside Rear C	hild Seat fitted not allowing full inspection	n of adult belt
Pass with rectification	Offside Front Windscreen wiper does no	t clear the windscreen effectively (3.4
(b) (ii))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #1	2018-12-27 16:49
MOT test number	866739490556
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 17 May 2024
Tax status	Valid until 1 June
Days left	34
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Duniuge 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-01-20
Last registration	2023-05-02
Complete history	<u>See info</u>



Registration #1	2016-01-20	28 mi
Registration #2	2018-12-27	17.594 mi
Registration #3	2020-01-10	36.288 mi
Registration #4	2020-01-10	36.288 mi
Registration #5	2021-01-19	50.699 mi
Registration #6	2021-01-19	50.701 mi
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 esi





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



Dimensions & weight	
Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1270 kg
Max. allowed weight	1695 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12