



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	Black
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-30
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	34
Total items failed	3

MOT #14 2023-10-17 15:29

MOT test number 393239666906

Result ✓ Passed

Next expiry date 2024-10-26

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13 2022-10-27 15:26

MOT test number 855244402660

Result ✓ Passed

MOT #12 2021-07-29 15:17

MOT test number 752890433650

Result ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2020-12-17 11:22

MOT test number 827681068255

Result ✓ Passed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #10**

2020-12-16 09:59

MOT test number

310025963003

Result**✗ Failed****MAJOR** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MOT #9**

2020-01-02 14:02

MOT test number

573332804885

Result**✓ Passed****Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #8** 2019-05-17 07:37**MOT test number** 288895294443**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2018-05-17 07:40**MOT test number** 441272301648**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-05-09 07:47**MOT test number** 155949994520**Result** ✓ Passed**MOT #5** 2016-05-05 10:12**MOT test number** 287232684318**Result** ✓ Passed**MOT #4** 2015-05-05 16:23**MOT test number** 927965525176**Result** ✓ Passed**MOT #3** 2015-05-05 16:23**MOT test number** 978185825160**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)



MOT #2 2014-05-07 14:05

MOT test number 117977024163

Result ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Front tyres worn on edges

MOT #1 2014-05-07 14:05

MOT test number 416447324160

Result ✗ Failed

Notice Under-trays fitted obscuring some underside components

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

Notice Front tyres worn on edges

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-05-20
Last registration	2023-10-17
Complete history	See info



Registration #1	2011-05-20	20 mi
Registration #2	2014-05-07	17.809 mi
Registration #3	2015-05-05	22.964 mi
Registration #4	2016-05-05	28.534 mi
Registration #5	2017-05-09	33.146 mi
Registration #6	2018-05-17	37.547 mi
Registration #7	2019-05-17	41.201 mi
Registration #8	2020-05-20	45.000 mi
Registration #9	2021-05-20	48.800 mi
Registration #10	2022-05-20	52.600 mi
Registration #11	2023-05-20	56.400 mi
Registration #12	2024-05-20	60.200 mi
Registration #13	2025-05-20	64.000 mi
Registration #14	2026-05-20	67.800 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1708102