



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Blue
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-12-16
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-18
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	17
Total items failed	13

MOT #20	2023-09-19 11:45
MOT test number	402443963881
Result	✓ Passed
Next expiry date	2024-09-18
<b>Advice</b>	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement both rear D-Link bushes (5.3.4 (a) (i))
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2022-09-13 15:07
MOT test number	944772550733
Result	✓ Passed
<b>Advice</b>	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both D-Link bushes (5.3.4 (a) (i))

MOT #18	2022-09-13 12:12
MOT test number	736224932608
Result	✗ Failed
<b>Fail</b>	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
<b>Advice</b>	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement Both D-Link bushes (5.3.4 (a) (i))
<b>Fail</b>	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #17**

2021-09-16 16:42

**MOT test number**

628385025580

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2021-09-16 09:09

**MOT test number**

873339651043

**Result**

✗ Failed

**Fail**

Offside Brake pipe excessively corroded front to rear (1.1.11 (c))

**Advice**

Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Offside Brake pipe excessively corroded front to rear (1.1.11 (c))

**Advice**

Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #15**

2020-09-12 09:06

**MOT test number**

843598563111

**Result**

✓ Passed

**MOT #14**

2019-09-17 13:58

**MOT test number**

175704924537

**Result**

✓ Passed

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-09-17 09:32**MOT test number** 707421399730**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #12** 2018-09-08 12:01**MOT test number** 334370290069**Result** ✓ Passed**MOT #11** 2017-09-19 14:44**MOT test number** 718096351224**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #10** 2017-09-19 12:37**MOT test number** 988592856068**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)

**MOT #9** 2016-06-21 08:23**MOT test number** 365265461167**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit on limit (4.1.E.1)**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' small crack (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit on limit (4.1.E.1)**MOT #8** 2015-06-08 10:04**MOT test number** 416239355194**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2014-06-18 14:38**MOT test number** 276749764442**Result** ✓ Passed**MOT #6** 2014-06-18 10:34**MOT test number** 947029164174**Result** ✗ Failed**Fail** Offside Front Tie bar/rod has excessive play in a pin/bush (2.4.G.2)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Front Exhaust system not adequately supported (7.1.1)**MOT #5** 2013-06-24 10:19**MOT test number** 287295373420**Result** ✓ Passed



MOT #4	2012-05-21 09:16
MOT test number	768032142146
Result	✓ Passed
MOT #3	2011-06-06 14:33
MOT test number	807157351151
Result	✓ Passed
MOT #2	2010-06-03 10:16
MOT test number	521084150141
Result	✓ Passed
MOT #1	2010-06-03 10:16
MOT test number	700664850130
Result	✗ Failed
<div>Pass with rectification</div> Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
18 September 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	18 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>KB070MV</b>
Plate since	2019-06-29
Current registration	<b>KB070MV</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-06-13
Last registration	2023-09-19
Complete history	<a href="#">See info</a>



Registration #1	2007-06-13	16 mi
Registration #2	2010-06-03	28.229 mi
Registration #3	2011-06-06	33.461 mi
Registration #4	2012-05-21	39.631 mi
Registration #5	2013-06-24	43.809 mi
Registration #6	2014-06-18	47.783 mi
Registration #7	2014-06-18	47.783 mi
Registration #8	2015-06-08	52.330 mi
Registration #9	2016-06-21	57.336 mi
Registration #10	2017-09-19	60.824 mi
Registration #11	2017-09-19	60.825 mi
Registration #12	2018-06-20	65.330 mi
Registration #13	2018-06-20	65.330 mi
Registration #14	2018-06-20	65.330 mi
Registration #15	2018-06-20	65.330 mi
Registration #16	2018-06-20	65.330 mi
Registration #17	2018-06-20	65.330 mi
Registration #18	2018-06-20	65.330 mi
Registration #19	2018-06-20	65.330 mi
Registration #20	2018-06-20	65.330 mi
Registration #21	2018-06-20	65.330 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20JV1118