



OE09VRF

report date: 2024-03-28

General information

Make	FIAT
Model	PANDA POP
Colour	White
Year of manufacture	2009
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-04
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-13
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	58
Total items failed	19

**MOT #19**

2024-04-22 09:14

MOT test number

169470444645

Result**✗ Failed**

- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Oil leak, but not excessive sump area from repair (8.4.1 (a) (i))
- Advice** Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Oil level on MIN
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge NO tread showing on inner edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Fail** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- Advice** Nearside exhaust clamp missing from rear box joint
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #18

2023-05-02 12:20

MOT test number

797699329551

Result**✓ Passed**

- Advice** Oil leak, but not excessive Engine sump (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2023-05-02 09:01

MOT test number

901266165420

Result**✗ Failed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Oil leak, but not excessive Engine sump (8.4.1 (a) (i))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**MOT #16**

2022-05-09 13:35

MOT test number

900612697314

Result**✓ Passed****Advice** Front Registration plate deteriorated but not likely to be misread Cracked (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 155/80/13 (5.2.3 (e))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #15**

2022-05-09 09:10

MOT test number

582859508260

Result**✗ Failed****Fail** Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Front Registration plate deteriorated but not likely to be misread Cracked (0.1 (b))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 155/80/13 (5.2.3 (e))**MOT #14**

2021-05-14 13:46

MOT test number

151058014418

Result**✓ Passed**

**MOT #13** 2020-03-19 10:09**MOT test number** 880299394226**Result** ✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12 2020-03-18 11:45**MOT test number** 283953462253**Result** ✗ Failed

- Fail** Offside Front Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11 2019-08-10 10:01**MOT test number** 501075772846**Result** ✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10** 2018-08-11 08:30**MOT test number** 570724715381**Result** ✓ Passed

- Advice** Coil spring corroded all four (5.3.1 (b) (i))
- Advice** Rear exhaust corroded
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #9 2018-08-11 08:30**MOT test number** 493035778554**Result** ✗ Failed

- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear exhaust corroded
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Coil spring corroded all four (5.3.1 (b) (i))

MOT #8 2017-08-21 08:18**MOT test number** 273230872143**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear exhaust corroded
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Rear coil spring corroded both (2.4.C.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front coil spring corroded both (2.4.C.1b)

**MOT #7** 2016-08-22 15:30**MOT test number** 370574357054**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Coolant leak radiator
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Coil spring corroded all four (2.4.C.1b)

MOT #6 2016-08-17 10:01**MOT test number** 402662241896**Result** ✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Coolant leak radiator
- Fail** Nearside Stop lamp not working (1.2.1b)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)
- Advice** Coil spring corroded all four (2.4.C.1b)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Rear Exhaust system not adequately supported clamp missing (7.1.1)
- Fail** Nearside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

MOT #5 2015-08-11 10:53**MOT test number** 469253125254**Result** ✓ Passed



MOT #4 2013-10-14 11:33

MOT test number 468767883205

Result ✓ Passed

MOT #3 2013-10-10 14:37

MOT test number 555423983293

Result ✗ Failed

Fail Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)

MOT #2 2013-05-23 15:40

MOT test number 746743643118

Result ✓ Passed

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Notice Rear exhaust box corroded

Notice Offside wiper blade split

MOT #1 2012-06-25 14:39

MOT test number 329347772192

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 May 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	13 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-07-15
Last registration	2024-04-22
Complete history	See info



Registration #1	2009-07-15	20 mi
Registration #2	2012-06-25	34.257 mi
Registration #3	2013-05-23	43.219 mi
Registration #4	2013-10-10	46.236 mi
Registration #5	2013-10-14	46.239 mi
Registration #6	2015-08-11	50.924 mi
Registration #7	2016-08-17	55.645 mi
Registration #8	2016-08-22	55.650 mi
Registration #9	2017-08-21	62.285 mi
Registration #10	2018-08-11	68.375 mi
Registration #11	2018-08-11	68.375 mi
Registration #12	2019-08-11	75.000 mi
Registration #13	2020-08-11	81.625 mi
Registration #14	2021-08-11	88.250 mi
Registration #15	2022-08-11	94.875 mi
Registration #16	2023-08-11	101.500 mi
Registration #17	2024-04-22	108.125 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5331536