





report date: 2024-03-28

General information

Make	BMW
Model	X6 XDRIVE30D
Colour	White
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	232 BHP
Max. torque	520 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	40.4 mpg
Consumption combined	34.5 mpg
CO2 emission	217 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 3

Date 2022-03-06

Pictures 43

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-12-15
------	------------

Pictures 42

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date	2021-09-27

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-06
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	9
Total items failed	6

MOT #15		2023-12-21 10:40
MOT test	number	693372112073
Result		✓ Passed
Next expi	y date	2025-01-06
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14		2023-12-18 12:41
MOT test number		615495487524
Result		X Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice Offside Rear Tyr	e worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Rear Coil sp	ring fractured or broken (5.3.1 (b) (i))	
Fail Supplementary rest	raint system warning lamp indicates a fault (7.1.6 (a))	
Advice Nearside Rear T	yre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front A (5.3.4 (a) (i))	anti-roll bar linkage pin or bush worn but not resulting in exc	cessive movement
Fail Nearside Front Susp (ii))	pension arm ball joint dust cover no longer prevents the ing	ress of dirt (5.3.4 (b)

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #13 2022-12-29 09:03

MOT test number 847776679751

Result \rightarrow Passed

Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #12 2022-01-07 14:16

MOT test number 721877217859

Result ✓ Passed

MOT #11 2021-11-23 15:39

MOT test number 456800146952

Result X Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #10 2020-11-25 13:11

MOT test number 954897021388

Result

Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2019-11-29 16:31

MOT test number 927280258597

MOT #8 2019-11-29 11:59

MOT test number 872362684460

Result X Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7	2018-11-26 13:49
MOT test number	139577806347
Result	✓ Passed
MOT #6	2017-11-28 10:50
MOT test number	941069745346
Result	✓ Passed
MOT #5	2016-11-29 14:59
MOT test number	346142357984
Result	✓ Passed
NOT #4	2015 11 24 00.22
MOT #4 MOT test number	2015-11-24 09:23 828055726539
Result	
Result	✓ Passed
MOT #3	2014-11-18 14:25
MOT test number	498792924321
Result	✓ Passed
MOT #2	2013-11-25 16:07
MOT test number	796719923393
Result	✓ Passed
MOT #1	2012-11-30 16:17
MOT test number	439195932339
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	6 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

n	\sim	-+.	i٥	h	r			O١	- 7
	OI	311	II S	n	ır	۱e	ΛI		

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)		ve?
manners and the same of the sa		

	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-30
Last registration	2023-12-21
Complete history	See info



Registration #1	2009-11-30	22 mi
Registration #2	2012-11-30	31.908 mi
Registration #3	2013-11-25	43.959 mi
Registration #4	2014-11-18	46.226 mi
Registration #5	2015-11-24	58.398 mi
Registration #6	2016-11-29	69.300 mi
Registration #7	2017-11-28	81.537 mi
Registration #8	2018-11-26	82.620 mi
Registration #9	2019-11-29	90.961 mi
Registration #10	2019-11-29	90.961 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
B 11 11 //10		
Registration #18		11.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1690 mm
Length	4877 mm
Wheel base	2933 mm
Kerb weight	2150 kg
Max. allowed weight	2675 kg

Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	4 page 12/1

Number of axles 2
Engine number 21157011