





General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT
Colour	Silver
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	9.3 seconds
0 - 60 mph	10.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	100 kW / 136 HP / 109 BHP
Max. torque	300 Nm at 1.600 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	120 g/km
CO2 label	С







Internet history

Entry 1

Date Pictures 2021-12-21

3

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-21
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #9		2024-01-06 11:00	
MOT test	number	925183232227	
Result		✓ Passed	
Next expi	ry date	2025-01-21	
Advice	Offside Rear Tyre slightly damaged sidewall damage and nail in tread (5	.2.3 (d) (ii))	
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))		
Advice	Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Advice	Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))		
Advice	Advice Offside Rear reg plate lamp dim		
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamp	s or light sources (4.7.1	



	report date: 2024-03-28	
MOT #8	2024-01-06 10:38	
MOT test number	757078006974	
Result	🗙 Failed	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))		
Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on o	uter edge (5.2.3 (e))	
Advice Offside Rear reg plate lamp dim		
Minor Nearside Registration plate lamp inoperative in the case of multiple lamp (b) (i))	ps or light sources (4.7.1	
Advice Offside Rear Tyre slightly damaged sidewall damage and nail in tread (5.2.3 (d) (ii))	
Fail Nearside Front Road wheel fractured (5.2.2 (a))		
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		

MOT #7	2023-01-20 09:41
MOT test number	965977354645
Result	✓ Passed

MOT #6	2022-01-22 14:10
MOT test number	664102945463
Result	✓ Passed
Advice Nearside Rear Tyre slightly damaged Side wall (5.2.3 (d) (ii))	

MOT #5	2020-12-15 10:11
MOT test number	567198801553
Result	✓ Passed
MOT #4	2010 12 20 15:04

MOT #4	2019-12-30 15:04
MOT test number	402946162811
Result	✓ Passed

LL63GVF





MOT #3	2018-12-18 12:40
MOT test number	419523668475
Result	✓ Passed
MOT #2	2017-12-18 11:50
MOT test number	169951316748
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #1	2016-12-05 16:11
MOT test number	579281616711

Result

CarCheck.co.uk

✓ Passed



Tax & MOT check

Tax due: 1 February 2025	✓ Taxed	Expires: 21 January 2025	√ МОТ
Tax status			Valid until 1 February
Days left			278
MOT expiry date			21 January 2025
Full MOT history			See MOT history
Tax calculation			
Vahiela elace		40	

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	K ATAPE
Туре	
Damage 2	AMPL
Date	
Category	AMPLE
Туре	

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	
formed methods	
Carrent registration	
Pate since	
Farle since Carrent registration	
Faite since Faite since Faite since	1111-21-22





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report here and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-12-27
Last registration	2024-01-06
Complete history	<u>See info</u>



Registration #1	2013-12-27	20 mi
Registration #2	2016-12-05	27.040 mi
Registration #3	2017-12-18	37.885 mi
Registration #4	2018-12-18	48.458 mi
Registration #5	2019-12-30	59.416 mi
Registration #6	2020-12-15	64.583 mi
Registration #7		11.777 mi
Registration #8		10.000 mil
Registration #9		11.117 mi
Registration #9 Registration #10		10.000 est

More info \rightarrow





Car features

The MERCEDES-BENZ factory car options list is only available in the premium report. S0225 Air conditioning S0295 -S0482 S0501 S0566 S0567 S0569 View the complete MERCEDES-BENZ factory list for this More info > vehicle <u>here</u>.

Safety ratings

NCAP rating	****
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2010 mm
Height	1542 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1505 kg
Max. allowed weight	2025 kg
Additional information	
Fuel tank capacity	50
Fuel delivery	Direct Injection
Number of doors	5
CarCheck.co.uk	page 12

Number of seats	5
Number of axles	2
Engine number	65190131839879