




report date: 2024-03-28

General information

Make	KIA
Model	RIO GS
Colour	Blue
Year of manufacture	2007
Top speed	105 mph
0 - 60 mph	14.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.2 mpg
CO2 emission	171 g/km
CO2 label	H








Internet history

Entry 1

Date	2021-06-03
Pictures	16
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-03-15
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	28
Total items failed	7

MOT #19 2024-02-16 12:56**MOT test number** 604496484214**Result** Passed**Next expiry date** 2025-03-15**Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Front Brake pad(s) wearing thin pads about 3mm (1.1.13 (a) (ii))**Advice** Offside Front steering rack fluid leak from gaitor**MOT #18** 2023-03-16 15:31**MOT test number** 730440985457**Result** Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))**MOT #17** 2022-03-14 09:04**MOT test number** 929332547639**Result** Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16** 2021-02-26 14:15**MOT test number** 485545629440**Result** ✓ Passed**Advice** Central Sop light not working**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15** 2021-02-23 14:42**MOT test number** 312624048280**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Central Sop light not working**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #14** 2020-02-24 15:31**MOT test number** 439523393665**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #13** 2019-02-26 15:00**MOT test number** 155225119720**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2019-02-25 14:51**MOT test number** 810112676444**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge On limit (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #11** 2018-02-27 12:09**MOT test number** 104655593769**Result** ✓ Passed**MOT #10** 2018-02-26 11:37**MOT test number** 544986921040**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement
Wishbone front bush (2.4.G.2)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2017-02-28 16:06**MOT test number** 262981623078**Result** ✓ Passed**MOT #8** 2017-02-24 14:28**MOT test number** 363945236335**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #7** 2016-02-29 11:16**MOT test number** 389729532781**Result** ✓ Passed



MOT #6	2015-07-06 14:56
MOT test number	779707785184
Result	✓ Passed
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5	2014-07-15 09:22
MOT test number	417616694109
Result	✓ Passed
Notice	N/s/f tyre wearing outer edge
Notice	Exhaust flexi starting to deteriorate
Notice	Nail in offside rear tyre

MOT #4	2013-07-19 09:07
MOT test number	606380303227
Result	✓ Passed
Notice	O/s/r tyre perished + worn to 2mm
Notice	N/s/r tyre worn to 2mm towards inner edge

MOT #3	2012-06-18 10:05
MOT test number	495010472114
Result	✓ Passed
Notice	O/s/f tyre slightly worn on inner edges

MOT #2	2011-06-16 09:23
MOT test number	895787861184
Result	✓ Passed
Notice	N/s/r tyre wearing thin outer edge



MOT #1	2010-06-18 10:59
MOT test number	183299160122
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 July
Days left	64
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-28
Current registration	XXXX XX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-07-30
Last registration	2024-02-16
Complete history	See info



Registration #1	2007-07-30	21 mi
Registration #2	2010-06-18	15.480 mi
Registration #3	2011-06-16	24.323 mi
Registration #4	2012-06-18	33.633 mi
Registration #5	2013-07-19	42.022 mi
Registration #6	2014-07-15	49.651 mi
Registration #7	2015-07-06	52.636 mi
Registration #8	2016-02-29	54.839 mi
Registration #9	2017-02-24	57.055 mi
Registration #10	2017-02-28	57.060 mi
Registration #11	2018-02-26	59.377 mi
Registration #12	2019-02-26	61.694 mi
Registration #13	2020-02-26	64.011 mi
Registration #14	2021-02-26	66.328 mi
Registration #15	2022-02-26	68.645 mi
Registration #16	2023-02-26	70.962 mi
Registration #17	2024-02-16	73.279 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1101 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4EE6H05827