



**YF63NBA**

report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER SD4 HSE LUXURY
Colour	Grey
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	11.2 seconds
0 - 60 mph	8.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 190 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-04-01
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-25
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	32
Total items failed	3

MOT #10	2024-03-21 09:45
MOT test number	654617812147
Result	✓ Passed
Next expiry date	2025-03-25
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #9	2023-03-22 10:51
MOT test number	910553258547
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 235/65 17 (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2023-03-22 08:54**MOT test number** 411333382352**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 235/65 17 (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2022-03-26 07:00**MOT test number** 140383836578**Result** ✓ Passed**MOT #6** 2021-06-29 08:55**MOT test number** 557772497306**Result** ✓ Passed**Advice** N\s\\r window damaged.**MOT #5** 2021-06-28 09:11**MOT test number** 460310042817**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** N\s\\r window damaged.**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #4

2019-06-26 14:10

MOT test number

980957905143

Result

✓ Passed

- Advice
- Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Brake pedal wearing smooth anti-slip rubber worn on edge (1.1.2 (c))
- Advice
- Under trays obscuring power steering components & fuel lines
- Advice
- Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice
- Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice
- Engine bay covers obscuring some components
- Advice
- Outer sill covers obscuring some prescribed areas
- Advice
- Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3** 2019-06-26 14:10**MOT test number** 850319434436**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake pedal wearing smooth anti-slip rubber worn on edge (1.1.2 (c))**Advice** Under trays obscuring power steering components & fuel lines**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Engine bay covers obscuring some components**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Outer sill covers obscuring some prescribed areas**MOT #2** 2017-07-21 07:17**MOT test number** 433913716687**Result** ✓ Passed**Advice** Nail in n/s/r tyre**MOT #1** 2016-11-25 17:02**MOT test number** 706101748132**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

Tax due:  
1 April 2025

✓  
**MOT**

Expires:  
25 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	25 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	YF63NBA
Plate since	2019-09-28
Current registration	YF63NBA
Plate since	2019-09-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-30
Last registration	2024-03-21
Complete history	<a href="#">See info</a>



Registration #1	2013-11-30	29 mi
Registration #2	2016-11-25	73.844 mi
Registration #3	2017-07-21	80.585 mi
Registration #4	2019-06-26	91.786 mi
Registration #5	2019-06-26	91.786 mi
Registration #6	2021-06-28	100.637 mi
Registration #7	2022-06-28	101.277 mi
Registration #8	2022-06-28	101.277 mi
Registration #9	2022-06-28	101.277 mi
Registration #10	2022-06-28	101.277 mi
Registration #11	2022-06-28	101.277 mi
Registration #12	2022-06-28	101.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ784152302224DT