





# General information

Make	PEUGEOT
Model	PARTNER HDI S L1 850
Colour	White
Year of manufacture	2011
Top speed	100 mph
0 - 60 mph	15.4 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg



# MOT history

MOT expiry date	2024-06-06
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	37
Total items failed	9

MOT #13	2023-06-07 16:16
MOT test number	174617112301
Result	✓ Passed
Next expiry date	2024-06-06

MOT #12		2023-06-02 12:45
MOT test	number	191936403532
Result		× Failed
MAJOR	Front Anti-roll bar ball joint excessively worn o/side and n/side (5.3.4 (a) (i))	
MAJOR	Offside Position lamp not working (4.2.1 (a) (ii))	
MAJOR	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
MAJOR	Horn not working (7.7 (a))	
MAJOR	Front Suspension arm pin or bush excessively worn o/side and n/side (5.3.4 (a	a) (i))
<b>DANGER</b> (8.2.2.2 (c		of other road users
MAJOR	Rear Registration plate lamp inoperative in the case of a single lamp or all lar	mps (4.7.1 (b) (ii))
MAJOR	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	





283584723695

MOT #11		2022-03-12 12:42
MOT test	number	654194404746
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread, spare whe	eel missing.
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
MOT #10		2022-03-11 10:07

MOT test number

Result		🗙 Failed
MAJOR	Offside Headlamp aim too low (4.1.2 (a))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
MAJOR	Offside Windscreen wiper not working (3.4 (a))	
MAJOR	Brake pedal anti-slip provision worn smooth (1.1.2 (c))	
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))	
Advice	Front registration plate deteriorated but not likely to be misread, spare wheel missing.	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Nearside Windscreen wiper not working (3.4 (a))	

MOT #9	2020-06-25 08:01
MOT test number	731383722493
Result	✓ Passed
MOT #8	2019-06-27 08:04

MOT test number	330247268366
Result	✓ Passed





MOT #7	2018-07-05 09:33
MOT test number	788146934116
Result	✓ Passed
МОТ #6	2017-06-28 09:28
MOT test number	123281153800
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #5	2016-07-08 15:51
MOT test number	396817438423
Result	✓ Passed

MOT #4		2015-11-13 12:47
MOT test	number	281796311194
Result		✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.	1i)
Advice	Nearside Front Tyre worn close to the legal limit worn on edges. (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit worn on edges. (4.1.E.1)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1)	i)
Advice	Offside Front Tyre worn close to the legal limit worn on edges. (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit worn on edges. (4.1.E.1)	





MOT #3	2015-11-12 10:56
MOT test number	161808593339
Result	🗙 Failed
Advice Nearside Rear Tyre worn close to the legal limit worn on edges. (4.1.E.1)	
FailOffside Front Front position lamp(s) not working (1.1.A.3b)	
Fail Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1	Li)
Advice Offside Front Tyre worn close to the legal limit worn on edges. (4.1.E.1)	
Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)	
Advice Offside Rear Tyre worn close to the legal limit worn on edges. (4.1.E.1)	
<b>Fail</b> Nearside Front Headlamp not working on dipped beam (1.7.5a)	
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5	5.1i)
Advice Nearside Front Tyre worn close to the legal limit worn on edges. (4.1.E.1)	
Fail Offside Front Headlamp aim too high (1.8)	

MOT #2	20	014-10-16 12:54
MOT test	number	705579384202
Result		✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Notice	Items removed from driver's view prior to test	






MOT #1	20	)14-10-16 12:54
MOT test number		496779584249
Result		🗙 Failed
Pass with rectification	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)	
Notice Items removed f	rom driver's view prior to test	
Pass with rectification	Brake pedal anti-slip provision missing (3.3.A.1b)	
Pass with rectification	Offside Stop lamp not working (1.2.1b)	
Pass with rectification	Offside Rear Direction indicator incorrect colour (1.4.A.2f)	
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)		



Tax & MOT check







### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
**********	
*******	
******	
**********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plata since	





### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In kilometers
Mileage registrations	13
First mileage registration	2011-11-15
Last registration	2023-06-07
Complete history	See info



Registration #1	2011-11-15	10 mi
Registration #2	2014-10-16	69.818 mi
Registration #3	2015-11-12	101.244 mi
Registration #4	2015-11-13	101.244 mi
Registration #5	2016-07-08	113.169 mi
Registration #6	2017-06-28	121.577 mi
Registration #7	2018-07-05	132.293 mi
Registration #8		11.117 esi
Registration #9		11.117 esi
Registration #10		11.117 esi
Registration #11		11.117 esi
Registration #12		11.777 esi
Registration #13		11.117 esi





### Car features

S0225	Air conditionin
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

# Dimensions & weight

Width	2112 mm
Height	1801 mm
Length	4380 mm
Kerb weight	1336 kg
Max. allowed weight	2185 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	JBCB0234269