



Mercedes-Benz



AI7KSK

report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI SE
Colour	Black
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN



Internet history

Entry 1	
Date	2021-09-02
Pictures	44
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #15	2023-01-14 09:58
MOT test number	718769607135
Result	✓ Passed
Next expiry date	2024-01-25

MOT #14	2022-01-10 13:12
MOT test number	227003634960
Result	✓ Passed

MOT #13	2021-01-26 10:47
MOT test number	757501627297
Result	✓ Passed

- Advice** Central Exhaust has a minor leak of exhaust gases Box (6.1.2 (a))
- Advice** Rear Brake pipe corroded, covered in grease or other material N/S + O/S (1.1.11 (c))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #12	2020-01-20 11:31
MOT test number	993279005899
Result	✓ Passed

MOT #11	2019-01-26 08:54
MOT test number	668952439794
Result	✓ Passed

**MOT #10**

2019-01-25 11:52

MOT test number

688430651511

Result**✗ Failed**

- MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))
- DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))
- MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- DANGEROUS** Offside Rear Hydraulic brake calliper damaged and braking performance affected (1.1.16 (a) (ii))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9

2018-01-25 14:04

MOT test number

783754957113

Result**✓ Passed**

- Advice** Offside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #8

2016-11-29 13:06

MOT test number

343748456545

Result**✓ Passed**

**MOT #7** 2015-11-16 14:31**MOT test number** 551349842900**Result** ✓ Passed**MOT #6** 2014-11-24 10:50**MOT test number** 429708424367**Result** ✓ Passed**MOT #5** 2014-11-24 10:50**MOT test number** 389198424318**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #4** 2013-11-29 10:55**MOT test number** 427913433479**Result** ✓ Passed**MOT #3** 2012-11-17 11:53**MOT test number** 309492922341**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2011-11-29 15:37**MOT test number** 266263031391**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-01-07 16:29
MOT test number	370027100031
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 A17KSK
Plate since	2019-03-28
Current registration	 A17KSK
Plate since	2019-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-12-15
Last registration	2023-01-14
Complete history	See info



Registration #1	2006-12-15	9 mi
Registration #2	2010-01-07	14.884 mi
Registration #3	2011-11-29	25.273 mi
Registration #4	2012-11-17	30.151 mi
Registration #5	2013-11-29	38.412 mi
Registration #6	2014-11-24	48.702 mi
Registration #7	2015-11-16	56.801 mi
Registration #8	2016-11-29	65.025 mi
Registration #9	2017-05-29	75.277 mi
Registration #10	2018-05-29	85.277 mi
Registration #11	2019-05-29	95.277 mi
Registration #12	2020-05-29	105.277 mi
Registration #13	2021-05-29	115.277 mi
Registration #14	2022-05-29	125.277 mi
Registration #15	2023-05-29	135.277 mi
Registration #16	2024-05-29	145.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	64094030254845