





report date: 2024-03-28

#### General information

| Make                | MERCEDES-BENZ                     |
|---------------------|-----------------------------------|
| Model               | ML ML300 CDI BLUEEFFICIENCY SPORT |
| Colour              | Black                             |
| Year of manufacture | 2011                              |
| Top speed           | 130 mph                           |
| 0 - 100 km/h        | 8.7 seconds                       |
| Gearbox             | 7 speed automatic                 |

## Engine & fuel consumption

| Power                   | 150 kW / 204 HP / 204 BHP |
|-------------------------|---------------------------|
| Max. torque             | 540 Nm at 1.600 rpm       |
| Engine capacity         | 2.987 cc                  |
| Cylinders               | 6                         |
| Fuel type               | Diesel                    |
| Consumption city        | 25.9 mpg                  |
| Consumption extra urban | 38.2 mpg                  |
| Consumption combined    | 32.5 mpg                  |
| CO2 emission            | 240 g/km                  |
| CO2 label               | L                         |



CarCheck.co.uk page 1/10



## Internet history

#### Entry 1

Date 2021-05-21

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/10



# MOT history

| MOT expiry date    | 2022-06-03 |
|--------------------|------------|
| MOT pass rate      | 89 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 1          |
| Total advice items | 10         |
| Total items failed | 1          |

| MOT #9   | 2021-06-04 06:39               |
|--|--------------------------------|
| MOT test number  | 271414972085                   |
| Result   | <b>✓</b> Passed                |
| Next expiry date   | 2022-06-03                     |
| Minor Nearside Front Outer Drive shaft joint constant velocity boot severely | / deteriorated (6.1.7 (g) (i)) |

| MOT #8   | 2021-06-04 06:39 |
|--|------------------|
| MOT test number  | 856533751061     |
| Result   | <b>X</b> Failed  |
| Minor Nearside Front Outer Drive shaft joint constant velocity boot se  Pass with rectification Nearside Front Position lamp not working (4) |                  |

| MOT #7   | 2020-07-30 08:14   |
|----------|--|
| MOT test | number 951861883674  |
| Result   | ✓ Passed   |
| Advice   | Hand brake effort only just met standard17%  |
| Advice   | Offside Rear Brake cable damaged but not to excess outer cover split and rusted (1.1.15 (a)) |

CarCheck.co.uk page 3/10



**MOT #4** 

dirt (2.5.C.1a)

Result

CarCheck.co.uk

MJ11FTE report date: 2024-03-28

2017-08-01 07:42

✓ Passed

page 4/10

MOT test number

S87458369407

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside hand brake cable outer cover deteriorated

MOT #5

MOT test number

761572293651

Result

✓ Passed

MOT test number 211676028351

Result Passed

Advice Nearside Front Outer Front constant velocity joint gaiter damaged, but preventing the ingress of

MOT #3 2016-06-30 08:35
MOT test number 538420467362

Result \( \sqrt{Passed} \)

Advice Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #2 2015-07-10 10:27
MOT test number 187131095104

**MOT #1** 2014-07-17 15:03

MOT test number 768478494124



#### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

| Date     |  |
|----------|--|
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



More info >

## Owner history

| o which initiating   |             |
|--|-------------|
| For how long did the current and previous owner(s) have this MERCEDES-BENZ? How mar MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. D report <a href="here">here</a> . |             |
|  |             |
|  |             |
|  |             |
|  |             |
| ********   |             |
|  |             |
| ************   |             |
| Plate changes  | More info > |
| See in this check if this MERCEDES-BENZ had different number plates.   |             |
| Number of plates   | ,           |
| Current registration   | UK NE       |
| Plate since  |             |
| Current registration   | NK NK       |
| Plate since  |             |
|  |             |

CarCheck.co.uk page 7/10



#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Courte et info    |  |

**Contact info** 


More info >

CarCheck.co.uk page 8/10



# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 11         |
| First mileage registration | 2011-06-01 |
| Last registration          | 2021-06-04 |
| Complete history           | See info   |



| Registration #1  | 2011-06-01 | 6 mi       |
|------------------|------------|------------|
| Registration #2  | 2014-07-17 | 30.555 mi  |
| Registration #3  | 2015-07-10 | 50.556 mi  |
| Registration #4  | 2016-06-30 | 72.841 mi  |
| Registration #5  | 2017-08-01 | 90.301 mi  |
| Registration #6  | 2018-07-31 | 101.770 mi |
| Registration #7  |            | 9.70 es    |
| Registration #8  |            | 11.777 es  |
| Registration #9  |            | 9.70 es    |
| Registration #10 |            | 11.777 es  |
| Registration #11 |            | 10.777 au  |

More info >

CarCheck.co.uk page 9/10



#### Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 |                 |
| 50482 |                 |
| 50501 |                 |
| 50566 |                 |
| 50567 |                 |
| 50569 |                 |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1911 mm |
|---------------------|---------|
| Height              | 1815 mm |
| Length              | 4781 mm |
| Wheel base          | 2915 mm |
| Kerb weight         | 2185 kg |
| Max. allowed weight | 2830 kg |

# Additional information

| Fuel tank capacity | 95 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| CarChaglegande     | maga 10/10       |

CarCheck.co.uk page 10/10

| Number of seats | 5              |
|-----------------|----------------|
| Number of axles | 2              |
| Engine number   | 64282041101600 |