



report date: 2024-03-28

General information

|                     |                                     |
|---------------------|-------------------------------------|
| Make                | VOLKSWAGEN                          |
| Model               | CC GT TDI BLUEMOTION TECHNOLOGY DSG |
| Colour              | Grey                                |
| Year of manufacture | 2014                                |
| Top speed           | 132 mph                             |
| 0 - 60 mph          | 9.8 seconds                         |
| Gearbox             | 6 speed Semi Auto                   |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 138 BHP             |
| Max. torque             | 320 Nm at 1.750 rpm |
| Engine capacity         | 1.968 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.1 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 53.3 mpg            |
| CO2 emission            | 134 g/km            |
| CO2 label               | E                   |







Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-04                  |
| Pictures      | 20                          |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk

**MOT history**

|                           |            |
|---------------------------|------------|
| <b>MOT expiry date</b>    | 2024-10-04 |
| <b>MOT pass rate</b>      | 78 %       |
| <b>MOT passed</b>         | 7          |
| <b>Failed MOT tests</b>   | 2          |
| <b>Total advice items</b> | 14         |
| <b>Total items failed</b> | 10         |

**MOT #9** 2023-10-04 11:18**MOT test number** 719213117691**Result** ✓ Passed**Next expiry date** 2024-10-04**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2022-10-03 12:32**MOT test number** 514276341991**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #7** 2021-10-01 14:36**MOT test number** 607048211593**Result** ✓ Passed**MOT #6** 2020-09-30 16:51**MOT test number** 347112698252**Result** ✓ Passed

**MOT #5**

2020-09-30 08:23

**MOT test number**

402566918874

**Result****✗ Failed****Advice**

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail**

Offside Rear Service brake excessively fluctuating (1.2.1 (e))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge inner edge worn/bald worn down to approx 3mm remaining (5.2.3 (e))

**Fail**

Offside Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Fail**

Nearside Front Lower Suspension arm pin or bush excessively worn rear bush mount (5.3.4 (a) (i))

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail**

Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

**Fail**

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail**

Rear Brake disc significantly and obviously worn both (1.1.14 (a) (i))

**Advice**

Rear Tyre slightly damaged/cracking or perishing both rear tyres miss shaped (5.2.3 (d) (ii))

**Advice**

Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))

**Fail**

Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail**

Offside Front Lower Suspension arm pin or bush excessively worn rear bush mount (5.3.4 (a) (i))

**MOT #4**

2019-10-04 15:01

**MOT test number**

545007018185

**Result****✓ Passed****MOT #3**

2018-10-05 15:44

**MOT test number**

504017499719

**Result****✓ Passed****Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))



|                 |   |
|-----------------|---|
| MOT #2          | 2018-10-01 13:51  |
| MOT test number | 199229479156  |
| Result          | ✗ Failed  |
| Fail            | Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))                  |
| Advice          | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                             |
| Fail            | Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii)) |

|                 |  |
|-----------------|--|
| MOT #1          | 2017-07-28 10:51   |
| MOT test number | 367037270920   |
| Result          | ✓ Passed   |
| Advice          | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice          | Oil leak   |
| Advice          | Offside Rear Tyre worn close to the legal limit (4.1.E.1)  |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
4 October 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 February          |
| <b>Days left</b>        | 278                             |
| <b>MOT expiry date</b>  | 4 October 2024                  |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | E          |
| <b>Single payment (12 months)</b>              | £ 180,00,- |
| <b>Single six month payment</b>                | £ 99,00,-  |
| <b>Total payable by 12 monthly instalments</b> | £ 189,00,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>ND14RFX</b> |
| Plate since          | 2024-03-28     |
| Current registration | <b>ND14RFX</b> |
| Plate since          | 2024-03-28     |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 11                       |
| First mileage registration | 2014-06-25               |
| Last registration          | 2023-10-04               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2014-06-25 | 8 mi       |
| Registration #2  | 2017-07-28 | 71.121 mi  |
| Registration #3  | 2018-10-01 | 87.942 mi  |
| Registration #4  | 2018-10-05 | 87.942 mi  |
| Registration #5  | 2019-10-04 | 93.675 mi  |
| Registration #6  | 2020-09-30 | 101.415 mi |
| Registration #7  | 2023-10-04 | 101.415 mi |
| Registration #8  | 2023-10-04 | 101.415 mi |
| Registration #9  | 2023-10-04 | 101.415 mi |
| Registration #10 | 2023-10-04 | 101.415 mi |
| Registration #11 | 2023-10-04 | 101.415 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 91%                             |
| Children       | 77%                             |
| Pedestrian     | 54%                             |
| Safety systems | 71%                             |
| Overall rating | 79%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 2090 mm |
| Height              | 1421 mm |
| Length              | 4902 mm |
| Wheel base          | 2710 mm |
| Kerb weight         | 1564 kg |
| Max. allowed weight | 2070 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 70 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |

|                 |            |
|-----------------|------------|
| Number of seats | 5          |
| Number of axles | 2          |
| Engine number   | CFFBJ33731 |