



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE
Colour	Purple
Year of manufacture	2015
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-01-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	24
Total items failed	6

MOT #11	2024-01-13 17:07
MOT test number	754506873553
Result	✓ Passed
Next expiry date	2025-01-19

MOT #10	2024-01-13 14:34
MOT test number	461636338608
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9	2023-01-18 14:23
MOT test number	622578228611
Result	✓ Passed
Advice	Rear back box bracket broken

MOT #8	2023-01-18 10:55
MOT test number	690647222682
Result	✗ Failed
Fail	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Rear back box bracket broken

**MOT #7**

2022-01-15 10:32

**MOT test number**

396222680718

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement  
perishing rear bush (5.3.4 (a) (i))

**Advice** Offside Rear Exhaust mounting defective still secure (6.1.2 (a))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement perishing  
rear bush (5.3.4 (a) (i))

**MOT #6**

2021-01-20 15:51

**MOT test number**

451263391772

**Result**

✓ Passed

**MOT #5**

2020-12-09 14:17

**MOT test number**

351719163217

**Result**

✓ Passed

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Nearside Front Nail in tyre

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Exhaust mounting defective (6.1.2 (a))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2020-12-09 11:54**MOT test number** 529921175117**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Nail in tyre**Fail** Nearside Front Obligatory mirror insecure (3.3 (b) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-12-11 10:27**MOT test number** 558320573448**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #2** 2019-01-14 16:45**MOT test number** 515866155211**Result** ✓ Passed



MOT #1	2018-08-21 09:31
MOT test number	117458339438
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
19 January 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	19 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-25
Last registration	2024-01-13
Complete history	<a href="#">See info</a>



Registration #1	2015-09-25	11 mi
Registration #2	2018-08-21	10.724 mi
Registration #3	2019-01-14	11.172 mi
Registration #4	2019-12-11	19.121 mi
Registration #5	2020-12-09	25.114 mi
Registration #6	2020-12-09	25.114 mi
Registration #7	2021-01-20	25.243 mi
Registration #8	2022-05-20	25.277 mi
Registration #9	2022-05-20	25.277 mi
Registration #10	2022-05-20	25.277 mi
Registration #11	2022-05-20	25.277 mi
Registration #12	2022-05-20	25.277 mi
Registration #13	2022-05-20	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM0107961