



report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-05
Pictures	27
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-28
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	16
Total items failed	7

MOT #14	2023-07-24 10:30
MOT test number	876728732783
Result	✓ Passed
Next expiry date	2024-07-28
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #13	2022-07-18 10:14
MOT test number	576577550229
Result	✓ Passed
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-07-29 12:41
MOT test number	735931627843
Result	✓ Passed
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2020-08-27 15:22**MOT test number** 239700693845**Result** ✓ Passed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10** 2020-08-27 14:25**MOT test number** 384944794992**Result** ✗ Failed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Offside Rear Rear fog lamp not working bulb holder not in unit (4.5.1 (a) (ii))**Fail** Nearside Rear Upper Position lamp not working (4.2.1 (a) (ii))**MOT #9** 2019-09-04 11:15**MOT test number** 770985972251**Result** ✓ Passed**MOT #8** 2018-07-24 10:54**MOT test number** 713674026435**Result** ✓ Passed**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #7** 2015-09-25 15:54**MOT test number** 741015303406**Result** ✓ Passed

**MOT #6** 2015-09-24 16:06**MOT test number** 275752945466**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #5** 2014-09-26 11:58**MOT test number** 446819164281**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2014-09-23 15:55**MOT test number** 575756264243**Result** ✗ Failed**Fail** Offside Windscreen wiper not operating automatically when switched on (8.2.1b)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Nearside Windscreen wiper not operating automatically when switched on (8.2.1b)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #3** 2014-03-21 10:15**MOT test number** 446890484005**Result** ✓ Passed**Notice** Universal rims fitted on all wheels**MOT #2** 2014-03-21 10:15**MOT test number** 558060684064**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Notice** Universal rims fitted on all wheels



MOT #1	2013-03-21 15:17
MOT test number	369590683009
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
28 July 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	28 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	RV10VEK
Plate since	2019-09-28
Current registration	RV10VEK
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-31
Last registration	2023-07-24
Complete history	See info



Registration #1	2010-03-31	8 mi
Registration #2	2013-03-21	22.140 mi
Registration #3	2014-03-21	38.424 mi
Registration #4	2014-09-23	47.010 mi
Registration #5	2014-09-26	47.010 mi
Registration #6	2015-09-24	62.643 mi
Registration #7	2015-09-25	62.684 mi
Registration #8	2018-07-24	73.488 mi
Registration #9	2023-07-24	75.277 mi
Registration #10	2023-07-24	75.277 mi
Registration #11	2023-07-24	75.277 mi
Registration #12	2023-07-24	75.277 mi
Registration #13	2023-07-24	75.277 mi
Registration #14	2023-07-24	75.277 mi
Registration #15	2023-07-24	75.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1505 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	7028193