



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Black
Year of manufacture	2009
Top speed	119 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-14
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-07-13
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	14
Total items failed	11

MOT #17	2023-07-03 13:56
MOT test number	994137550438
Result	✓ Passed
Next expiry date	2024-07-13
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16	2022-07-01 11:31
MOT test number	564209582403
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

MOT #15	2022-07-01 11:31
MOT test number	599874363477
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))

**MOT #14** 2021-07-14 08:59**MOT test number** 383854368224**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-09-01 12:12**MOT test number** 539589870374**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2020-09-01 09:57**MOT test number** 664330882505**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2019-09-09 15:53**MOT test number** 251697372761**Result** ✓ Passed**MOT #10** 2019-09-07 11:10**MOT test number** 246669086924**Result** ✗ Failed**Fail** Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #9** 2018-09-06 10:08**MOT test number** 524259250802**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-09-11 11:28**MOT test number** 691774506944**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-09-11 10:30**MOT test number** 951810470852**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-09-08 13:40**MOT test number** 773394291247**Result** ✓ Passed**MOT #5** 2015-08-25 12:54**MOT test number** 411555519134**Result** ✓ Passed**Advice** Tyre worn close to the legal limit offside front (4.1.E.1)

**MOT #4** 2015-08-25 09:11**MOT test number** 181762693641**Result** ✗ Failed

**Fail** Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt offside front (2.4.G.2)

**Fail** Tyre has a cut in excess of the requirements deep enough to reach the ply or cords nearside front (4.1.D.1a)

**Fail** Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt nearside front (2.4.G.2)

**Advice** Tyre worn close to the legal limit offside front (4.1.E.1)

**MOT #3** 2014-08-29 10:07**MOT test number** 258301744211**Result** ✓ Passed**MOT #2** 2013-08-07 12:16**MOT test number** 496299113240**Result** ✓ Passed**MOT #1** 2012-08-09 13:25**MOT test number** 445052122243**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>PN59CKG</b>
Plate since	2024-03-28
Current registration	 <b>PN59CKG</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-11
Last registration	2023-07-03
Complete history	<a href="#">See info</a>



Registration #1	2009-09-11	22 mi
Registration #2	2012-08-09	32.706 mi
Registration #3	2013-08-07	38.064 mi
Registration #4	2014-08-29	48.009 mi
Registration #5	2015-08-25	55.733 mi
Registration #6	2015-08-25	55.733 mi
Registration #7	2016-09-08	61.485 mi
Registration #8	2017-09-11	65.669 mi
Registration #9	2017-09-11	65.669 mi
Registration #10	2018-09-06	69.823 mi
Registration #11	2019-09-06	75.377 mi
Registration #12	2019-09-06	75.377 mi
Registration #13	2019-09-06	75.377 mi
Registration #14	2019-09-06	75.377 mi
Registration #15	2019-09-06	75.377 mi
Registration #16	2019-09-06	75.377 mi
Registration #17	2019-09-06	75.377 mi
Registration #18	2019-09-06	75.377 mi
Registration #19	2019-09-06	75.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 173871