



report date: 2024-03-29

## General information

Make	VOLVO
Model	XC90 D5 POWERPULSE R-DESIGN PRO AWD
Colour	Silver
Year of manufacture	2018
Top speed	137 mph
0 - 60 mph	7.4 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	35.3 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-01-27
Pictures	11
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

**MOT history**

<b>MOT expiry date</b>	2025-03-22
<b>MOT pass rate</b>	100 %
<b>MOT passed</b>	4
<b>Failed MOT tests</b>	0
<b>Total advice items</b>	6
<b>Total items failed</b>	0

<b>MOT #4</b>	2024-03-18 09:37
<b>MOT test number</b>	727639799043
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2025-03-22

<b>MOT #3</b>	2023-03-23 11:47
<b>MOT test number</b>	552826526399
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge 235-55-19 (5.2.3 (e))

<b>MOT #2</b>	2022-03-19 12:10
<b>MOT test number</b>	835691323253
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing cracked (5.2.3 (d) (ii))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing cracked (5.2.3 (d) (ii))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened pitted (1.1.14 (a) (iii))
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing cracked (5.2.3 (d) (ii))



MOT #1	2021-09-30 12:21
MOT test number	655560054396
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 April 2025

✓  
**MOT**

**Expires:**  
22 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	22 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>First licence fee (12 months)</b>	£ 645,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 1.040,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>SJ68ABX</b>
Plate since	2024-03-29
Current registration	<b>SJ68ABX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-10-29
Last registration	2024-03-18
Complete history	<a href="#">See info</a>



Registration #1	2018-10-29	16 mi
Registration #2	2021-09-30	21.298 mi
Registration #3	2022-03-29	21.298 mi
Registration #4	2022-03-29	21.298 mi
Registration #5	2022-03-29	21.298 mi
Registration #6	2022-03-29	21.298 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Wheel base	2984 mm
Kerb weight	2009 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	2551350