



HYUNDAI




report date: 2024-10-06

General information

Make	HYUNDAI
Model	SONATA CRTD
Colour	Grey
Year of manufacture	2008
Top speed	124 mph
0 - 60 mph	11.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	304 Nm at 2.000 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	38.7 mpg
CO2 emission	191 g/km
CO2 label	J





Internet history

Entry 2

Date	2021-06-16
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-05-26
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2021-11-26
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	16
Total items failed	8

MOT #15 2020-11-27 11:48

MOT test number 727390419677

Result ✓ Passed

Next expiry date 2021-11-26

Advice Offside Play in steering rack inner joint(s)

MOT #14 2020-11-27 11:48

MOT test number 129936067999

Result ✗ Failed

Pass with rectification Nearside Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Offside Play in steering rack inner joint(s)

MOT #13 2019-10-15 12:05

MOT test number 966518605868

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Play in steering rack inner joint(s)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #12 2019-10-15 12:05

MOT test number 648688395692

Result ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Play in steering rack inner joint(s)
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #11 2018-10-11 14:47

MOT test number 578592490272

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2017-09-15 14:27

MOT test number 455315712225

Result ✓ Passed

MOT #9 2017-09-15 08:03

MOT test number 857869941959

Result ✗ Failed

- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Rear Fuel pipe insecure fuel filter housing (7.2.1)
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #8 2016-09-16 14:29

MOT test number 655425612905

Result ✓ Passed



MOT #7 2015-09-16 10:59

MOT test number 842015779577

Result ✔ Passed

Advice Nearside front tyre worn on outer edge

Advice Offside front tyre worn on edges

Advice Both front tyres under inflated

MOT #6 2014-09-17 11:12

MOT test number 607790764297

Result ✔ Passed

MOT #5 2013-09-17 17:51

MOT test number 856640963212

Result ✔ Passed

MOT #4 2013-09-17 12:09

MOT test number 338380463222

Result ✘ Failed

Fail Offside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Notice Offside rear tyre worn on inner edge

Fail Nearside Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Inner Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2013-01-14 16:06

MOT test number 489334713084

Result ✔ Passed



MOT #2	2012-01-12 16:10
MOT test number	736222912059
Result	✓ Passed
Notice	All four tyres are slightly perished
Notice	The front brake pads are approx 80% worn

MOT #1	2011-01-24 17:06
MOT test number	138954121026
Result	✓ Passed



Tax & MOT check

×
Untaxed

Tax expired:
28 October 2021

×
MOT

Expired:
26 November 2021

Tax status	Expired at 28 October 2021
Days left	1108 days too late
MOT expiry date	26 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-




Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-09-20
Current registration	XXXXXX
Plate since	2024-09-20

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-01-31
Last registration	2020-11-27
Complete history	See info



Registration #1	2008-01-31	10 mi
Registration #2	2011-01-24	8.687 mi
Registration #3	2012-01-12	11.089 mi
Registration #4	2013-01-14	13.724 mi
Registration #5	2013-09-17	15.767 mi
Registration #6	2013-09-17	15.767 mi
Registration #7	2014-09-17	21.897 mi
Registration #8	2015-09-16	27.425 mi
Registration #9	2016-09-16	32.931 mi
Registration #10	2017-09-16	38.437 mi
Registration #11	2018-09-16	43.943 mi
Registration #12	2019-09-16	49.449 mi
Registration #13	2020-09-16	54.955 mi
Registration #14	2021-09-16	60.461 mi
Registration #15	2022-09-16	65.967 mi
Registration #16	2023-09-16	71.473 mi
Registration #17	2024-09-16	76.979 mi
Registration #18	2025-09-16	82.485 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1475 mm
Length	4800 mm
Wheel base	2700 mm
Kerb weight	1613 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles

2

Engine number

D4EA7417481