



report date: 2024-03-28

General information

Make	KIA
Model	CEED GT-LINE ISG
Colour	Yellow
Year of manufacture	2017
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.7 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-26
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	13
Total items failed	0

MOT #7	2023-10-17 14:47
MOT test number	824759683701
Result	✓ Passed
Next expiry date	2024-10-26

MOT #6	2023-10-17 09:13
MOT test number	510764871276
Result	✗ Failed
<p>DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure 225/45/17 (5.2.3 (d) (ii))</p> <p>DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 225/45/17 (5.2.3 (d) (ii))</p>	

MOT #5	2022-10-21 09:22
MOT test number	764727233045
Result	✓ Passed

**MOT #4**

2021-10-22 12:45

MOT test number

943242854461

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement
Wishbone rear bush starting to split (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3

2021-10-22 09:14

MOT test number

967972306869

Result

✗ Failed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement
Wishbone rear bush starting to split (5.3.4 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2

2020-10-27 22:26

MOT test number

933124419006

Result

✓ Passed

MOT #1

2020-01-11 09:06

MOT test number

338952048277

Result

✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 October 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	26 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	MM66HYT
Plate since	2019-09-29
Current registration	MM66HYT
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-02-06
Last registration	2023-10-17
Complete history	See info



Registration #1	2017-02-06	7 mi
Registration #2	2020-01-11	15.057 mi
Registration #3	2020-10-27	16.887 mi
Registration #4	2020-10-27	16.887 mi
Registration #5	2021-10-22	19.252 mi
Registration #6	2023-10-17	19.252 mi
Registration #7	2023-10-17	19.252 mi
Registration #8	2023-10-17	19.252 mi
Registration #9	2023-10-17	19.252 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	88%
Pedestrian	61%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1402 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G3LCHP080123