



General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	2010
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	H





MOT history

MOT expiry date	2025-03-13
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	28
Total items failed	12

MOT #17	2024-03-13 09:59
MOT test number	825143310450
Result	✓ Passed
Next expiry date	2025-03-13
Advice	Both rear tyres cracking badly
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Heat shield insecure

MOT #16	2024-03-11 16:48
MOT test number	749925411453
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Headlamp aim too low (4.1.2 (a))
Advice	Both rear tyres cracking badly
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Exhaust has a major leak of exhaust gases middle (6.1.2 (a))
Advice	Heat shield insecure
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #15** 2023-03-14 11:59**MOT test number** 932180149748**Result** ✓ Passed**Advice** Nearside Rear reverse light lens missing**MOT #14** 2023-03-14 08:45**MOT test number** 381892457267**Result** ✗ Failed**Advice** Nearside Rear reverse light lens missing**Fail** Front Inner Brake pad(s) less than 1.5 mm thick NSF / OSF (1.1.13 (a) (ii))**MOT #13** 2022-02-25 13:48**MOT test number** 343721336578**Result** ✓ Passed**MOT #12** 2021-03-04 11:34**MOT test number** 930040079150**Result** ✓ Passed**MOT #11** 2021-03-01 16:07**MOT test number** 452010960553**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Direction indicator incorrect colour both rear (4.4.3 (a))**Advice** Rear heat shield loose**Fail** Exhaust system insecure rear (6.1.2 (a))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #10**

2020-03-04 10:44

**MOT test number**

441941573961

**Result**

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Nail in tyre is leaking
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2020-03-04 10:44

**MOT test number**

853156450203

**Result**

✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Pass with rectification** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Nail in tyre is leaking
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #8**

2019-02-27 09:55

**MOT test number**

963218031210

**Result**

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-02-28 10:11**MOT test number** 280735610822**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-02-16 11:28**MOT test number** 981014111738**Result** ✓ Passed**MOT #5** 2017-02-16 10:28**MOT test number** 131260471294**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #4** 2016-01-28 11:06**MOT test number** 971748502267**Result** ✓ Passed**MOT #3** 2015-02-02 13:07**MOT test number** 665753935054**Result** ✓ Passed**MOT #2** 2014-02-14 17:20**MOT test number** 768055444025**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #1	2013-02-27 08:11
MOT test number	937258353089
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
13 March 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	13 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>YG10SFF</b>
Plate since	2019-03-28
Current registration	<b>YG10SFF</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-30
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2010-03-30	8 mi
Registration #2	2013-02-27	34.675 mi
Registration #3	2014-02-14	46.374 mi
Registration #4	2015-02-02	59.687 mi
Registration #5	2016-01-28	74.050 mi
Registration #6	2017-02-16	78.350 mi
Registration #7	2017-02-16	78.354 mi
Registration #8	2018-02-28	83.211 mi
Registration #9	2019-02-27	86.183 mi
Registration #10	2019-03-20	86.217 mi
Registration #11	2019-03-20	86.217 mi
Registration #12	2019-03-20	86.217 mi
Registration #13	2019-03-20	86.217 mi
Registration #14	2019-03-20	86.217 mi
Registration #15	2019-03-20	86.217 mi
Registration #16	2019-03-20	86.217 mi
Registration #17	2019-03-20	86.217 mi
Registration #18	2019-03-20	86.217 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1347 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AL29261