



TOYOTA

RL52WOH


report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVTI GX
Colour	Blue
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	146 BHP
Max. torque	193 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg





Internet history

Entry 1

Date	2021-08-28
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #22** 2021-12-02 14:30**MOT test number** 435988443583**Result** ✓ Passed**Next expiry date** 2022-12-07**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded face (1.1.14 (a) (ii))**Advice** Nearside Front brake back plate corroded**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Central Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front brake back plate missing corroded away**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #21** 2021-11-30 13:21**MOT test number** 494897276978**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front brake back plate corroded**Advice** Central Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened corroded face (1.1.14 (a) (ii))**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front brake back plate missing corroded away**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #20** 2020-12-07 15:12**MOT test number** 744050692490**Result** ✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))

MOT #19 2019-11-26 14:54**MOT test number** 567194629452**Result** ✓ Passed

Advice Middle to rear exhaust joint heavily corroded

MOT #18 2019-11-25 14:27**MOT test number** 849733928135**Result** ✗ Failed

Advice Middle to rear exhaust joint heavily corroded

MAJOR Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Both rear tyres wearing low

**MOT #17** 2018-11-28 14:10**MOT test number** 419040184807**Result** ✓ Passed

- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Passenger seat(s) missing at time of test
- Advice** Front Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** EML light on dash

MOT #16 2017-12-05 12:56**MOT test number** 303190328049**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Vehicle structure has slight corrosion n/s/f & o/s/f inner sills/floor (6.1.B.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Oil leak

**MOT #15**

2017-12-01 11:06

MOT test number

936513642520

Result

✗ Failed

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail

Nearside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

Advice

Vehicle structure has slight corrosion n/s/f & o/s/f inner sills/floor (6.1.B.2)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Front Oil leak

Fail

Offside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

MOT #14

2016-12-06 14:58

MOT test number

670725856334

Result

✓ Passed

Advice

Offside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice

Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #13

2015-12-04 13:03

MOT test number

483365090437

Result

✓ Passed

Advice

Exhaust system thin

MOT #12

2014-12-08 11:47

MOT test number

607782544306

Result

✓ Passed

**MOT #11** 2014-12-08 11:47**MOT test number** 918302144385**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #10** 2013-12-02 16:59**MOT test number** 836186033398**Result** ✓ Passed**Notice** E.M.L On**MOT #9** 2013-12-02 16:59**MOT test number** 198216533316**Result** ✗ Failed**Notice** E.M.L On**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #8** 2012-11-27 14:41**MOT test number** 155522532323**Result** ✓ Passed**Notice** N\s rear tyre slightly perished**Notice** Wet conditions**MOT #7** 2011-12-05 12:19**MOT test number** 495829131312**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)


**MOT #6** 2010-12-01 10:01**MOT test number** 771295330382**Result** ✓ Passed**Notice** Rear exhaust clamp corroded**MOT #5** 2009-11-23 16:02**MOT test number** 460797829466**Result** ✓ Passed**Notice** Rack and pinion rubber mounts worn**Advice** Front brake disc slightly scored (3.5.1h)**Notice** Rear exhaust clamp rusty**MOT #4** 2008-11-12 09:05**MOT test number** 670337718356**Result** ✓ Passed**MOT #3** 2007-11-29 09:12**MOT test number** 421893437319**Result** ✓ Passed**Notice** Brake reservoir low**MOT #2** 2006-11-30 09:25**MOT test number** 764124236337**Result** ✓ Passed**MOT #1** 2005-12-02 10:43**MOT test number** 934116035378**Result** ✓ Passed**Notice** Rack ' pinion rubber mounts worn



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-12-03
Last registration	2021-12-02
Complete history	See info



Registration #1	2002-12-03	14 mi
Registration #2	2005-12-02	16.782 mi
Registration #3	2006-11-30	21.934 mi
Registration #4	2007-11-29	28.356 mi
Registration #5	2008-11-12	33.248 mi
Registration #6	2009-11-23	40.839 mi
Registration #7	2010-12-01	47.914 mi
Registration #8	2011-12-05	52.737 mi
Registration #9	2012-11-27	58.227 mi
Registration #10	2013-12-02	70.261 mi
Registration #11	2014-12-08	77.952 mi
Registration #12	2015-12-02	85.643 mi
Registration #13	2016-12-02	93.334 mi
Registration #14	2017-12-02	101.025 mi
Registration #15	2018-12-02	108.716 mi
Registration #16	2019-12-02	116.407 mi
Registration #17	2020-12-02	124.098 mi
Registration #18	2021-12-02	131.789 mi
Registration #19	2022-12-02	139.480 mi
Registration #20	2023-12-02	147.171 mi
Registration #21	2024-03-28	154.862 mi
Registration #22	2024-03-28	154.862 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1AZ0898312