



report date: 2024-03-28

General information

Make	MINI
Model	JOHN COOPER WORKS
Colour	Grey
Year of manufacture	2015
Top speed	153 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	320 Nm at 4.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-03-23
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	17
Total items failed	0

MOT #9	2024-03-18 10:44
MOT test number	853235959317
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive weeping from engine, oil on undertray (8.4.1 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing date stamp on tyre older than car (5.2.3 (d) (ii))

MOT #8	2024-03-15 10:16
MOT test number	651475081700
Result	✗ Failed
MAJOR	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
MAJOR	Exhaust emissions - engine idle speed too high (8.2.1.2 (e))
DANGEROUS	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive weeping from engine, oil on undertray (8.4.1 (a) (i))
DANGEROUS	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing date stamp on tyre older than car (5.2.3 (d) (ii))



MOT #7	2023-03-18 08:42
---------------	------------------

MOT test number	105439685391
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2022-03-19 13:32
---------------	------------------

MOT test number	613743317955
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2021-03-24 12:46
---------------	------------------

MOT test number	510212154256
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2019-08-16 09:31
---------------	------------------

MOT test number	891056571815
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2019-08-15 10:54
---------------	------------------

MOT test number	698396877944
------------------------	--------------

Result	✗ Failed
---------------	----------

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure
(5.2.3 (d) (ii))

MOT #2	2018-08-15 12:01
---------------	------------------

MOT test number	898715565482
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice Items removed from driver's view prior to test



MOT #12018-08-14 11:50

MOT test number746488379808

Result		✗ Failed
Advice	Nearside Front tyre worn on edge nearly to cords	
Advice	Items removed from driver's view prior to test	
DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Advice	Offside Front Nail in tyre	
Advice	Front tyres wearing heavily inside and outside edges	



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-08-21
Last registration	2024-03-18
Complete history	See info



Registration #1	2015-08-21	20 mi
Registration #2	2018-08-14	17.857 mi
Registration #3	2018-08-15	17.857 mi
Registration #4	2019-08-15	23.279 mi
Registration #5	2019-08-16	23.279 mi
Registration #6	2019-08-20	25.277 mi
Registration #7	2019-08-20	25.277 mi
Registration #8	2019-08-20	25.277 mi
Registration #9	2019-08-20	25.277 mi
Registration #10	2019-08-20	25.277 mi
Registration #11	2019-08-20	25.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1414 mm
Length	3874 mm
Wheel base	1932 mm
Kerb weight	1295 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	F5581161
---------------	----------