



### General information

Make	MINI
Model	MINI (R60) ONE D
Colour	Black
Year of manufacture	2011
Top speed	106 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С





# Internet history

Entry	1
Date	


2021-09-22

Pictures

Listing price

View report

17



source: autotrader.co.uk



# MOT history

MOT expiry date	2025-02-15
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #13		2024-02-05 10:48
MOT test	number	755787351738
Result		Passed
Next expi	ry date	2025-02-15
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-02-16 12:20
MOT test number	442751331772
Result	✓ Passed
MOT #11	2021-09-17 13:47

	2021 05 17 15.47
MOT test number	239217445348
Result	✓ Passed





MOT #10	2021-09-15 16:50
MOT test number	631738418108
Result	🗙 Failed
<b>Fail</b> Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Central Front Supplementary restraint system warning lamp indicates a fault (7.1.6 (	a))
Advice Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #9	2020-12-11 11:03
MOT test number	365169380955
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #8	2019-06-13 16:00
MOT test number	906425267221
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #7		2019-06-12 08:57
MOT test number		561393668081
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))		
Fail Nearside Rear Shoc	k absorbers has a serious fluid leak (5.3.2 (b))	





МОТ #6	2018-06-13 08:32
MOT test number	627413531286
Result	✓ Passed
MOT #5	2018-06-12 15:17
MOT test number	456400024946
Result	🗙 Failed
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MOT #4	2017-11-22 10:08
MOT test number	896725497843
Result	✓ Passed
Advice Nearside Rear tyre down to 3 mm at outer side	
Advice Brake pad warning light showing	
Advice Rear brake pads getting lower	
Advice Nearside Front tyre worn down on edges, close to cording, advise to replace now	

MOT #3		2016-12-13 10:54
MOT test	number	561639102667
Result		✓ Passed
Advice	Both front wiper blades smeary.	
Advice	Nearside front tyre wearing fast on the edges, Still okay at present.	
Advice	Nearside rear tyre has worn down to 4MM.	





MOT #2		2015-12-02 10:08
MOT test	number	246123087333
Result		✓ Passed
Advice	Front tyres starting to wear on edges	
Advice	Offside Rear tyre starting to wear on inner edge	

MOT #1	2014-10-31 11:07
MOT test number	489584604453
Result	✓ Passed



### Tax & MOT check

<b>Tax due:</b> 1 April 2025	√ Taxed	<b>Expires:</b> 15 February 2025	✓ МОТ
Tax status			Valid until 1 April
Days left			338
MOT expiry date			15 February 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
*******	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-10-31
Last registration	2024-02-05
Complete history	See info



Registration #1	2011-10-31	23 mi
Registration #2	2014-10-31	36.622 mi
Registration #3	2015-12-02	49.089 mi
Registration #4	2016-12-13	64.273 mi
Registration #5	2017-11-22	79.386 mi
Registration #6	2018-06-12	83.673 mi
Registration #7	2018-06-13	83.674 mi
Registration #8	2019-06-12	94.926 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 mi
Registration #15		11.777 mi

More info  $\rightarrow$ 





#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1820 kg
Additional information	
Fuel tank capacity	47
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	73527868