



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 30 L1H1 100 SWB PV
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT #14 2019-10-18 16:11**MOT test number** 380134641334**Result** ✗ Failed**MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**DANGEROUS** Offside Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #13** 2018-10-13 13:04**MOT test number** 680858996089**Result** ✓ Passed**MOT #12** 2018-10-12 14:10**MOT test number** 294211484702**Result** ✗ Failed**MAJOR** Windscreen washer not working (3.5 (a))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #11** 2017-10-13 14:50**MOT test number** 937820826728**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #10** 2016-10-14 13:34**MOT test number** 176236875588**Result** ✓ Passed

- Advice** Oil leak
- Advice** Nearside Front Nail in tyre
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Nail in tyre x3

MOT #9 2016-10-13 07:51**MOT test number** 777396557141**Result** ✗ Failed

- Advice** Oil leak
- Advice** Nearside Front Nail in tyre
- Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Rear Nail in tyre x3
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #8 2015-03-16 14:17**MOT test number** 569245175051**Result** ✓ Passed

**MOT #7** 2015-03-12 14:09**MOT test number** 748461975018**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2014-03-12 10:26**MOT test number** 517031474011**Result** ✓ Passed**MOT #5** 2014-03-05 14:38**MOT test number** 125404964089**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Body has a sharp edge caused by damage (6.1.C.1)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Rear Direction indicator not working (1.4.A.2c)**Fail** Offside Rear Body has a sharp edge caused by damage (6.1.C.1)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2013-02-20 15:24**MOT test number** 657151653065**Result** ✓ Passed

**MOT #3** 2012-03-05 11:18**MOT test number** 135545062074**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Noise from rear axle when vehicle moving**MOT #2** 2011-03-10 10:22**MOT test number** 199509361049**Result** ✓ Passed**MOT #1** 2011-03-02 13:13**MOT test number** 158291561417**Result** ✗ Failed**Fail** Steering arm has relative movement at its fixings (2.2.B.1h)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	LV08EUE
Plate since	2019-09-29
Current registration	LV08EUE
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-03-17
Last registration	2019-10-18
Complete history	See info



Registration #1	2008-03-17	12 mi
Registration #2	2011-03-02	20.542 mi
Registration #3	2011-03-10	20.550 mi
Registration #4	2012-03-05	32.604 mi
Registration #5	2013-02-20	51.180 mi
Registration #6	2014-03-05	74.185 mi
Registration #7	2014-03-12	74.186 mi
Registration #8	2015-03-12	86.267 mi
Registration #9	2016-03-12	98.348 mi
Registration #10	2017-03-12	110.429 mi
Registration #11	2018-03-12	122.510 mi
Registration #12	2019-03-12	134.591 mi
Registration #13	2020-03-12	146.672 mi
Registration #14	2021-03-12	158.753 mi
Registration #15	2022-03-12	170.834 mi

More info >



Dimensions & weight

Width	2508 mm
Height	2254 mm
Length	4963 mm
Kerb weight	1845 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ10242931