





report date: 2024-03-29

### General information

Make	BMW
Model	316 316I SE
Colour	Silver
Year of manufacture	1997
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	102 BHP
Max. torque	150 Nm at 3.900 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg



CarCheck.co.uk page 1/12



R637AHJ report date: 2024-03-29

## Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Lifety 1	
Date	2021-07-31
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

NAC	\Т	بہا: حا	L
MC	ノレ	nis	tory

MOT expiry date	2024-11-01
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	19
Total items failed	7

MOT #20	2023-11-02 13:33
MOT test number	128376647486
Result	✓ Passed
Next expiry date	2024-11-01

MOT #19	2022-09-22 12:27
MOT test number	579161339143
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #18	2022-09-21 10:30
MOT test number	474165990722
Result	<b>X</b> Failed
Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Offside Rear Hydraulic brake cylinder leaking hydraulic fluid (1.1.16 (b) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #17		2021-09-29 11:53
MOT test nu	mber	739192862553
Result		✓ Passed
<b>Advice</b> 0	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #16		2020-12-18 14:01
MOT test	number	336215854984
Result		<b>✓</b> Passed
MOT #15		2019-12-17 14:13
MOT test	number	710972017659
Result		✓ Passed
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Central Front Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #14	2018-12-05 13:52
MOT test number	878916859713
Result	✓ Passed

1100011		V i dosed
MOT #13		2017-12-19 15:01
MOT test	number	429798318582
Result		<b>✓</b> Passed
Advice	Oil leak	
Advice	Items removed from driver's view prior to test	

MOT #12	2016-09-12 11:31
MOT test number	558016357457
Result	<b>✓</b> Passed
Advice O/s/n/s front and n/s rear tyres outer walls perished.	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #11 2015-09-19 07:29
MOT test number 361007212521

Result J Passed

**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**Advice** N/s/f o/s/f and n/s/r tyres have cracking to the sidewalls

**Advice** Nearside Rear rear brake fluctuating, but not excessively (3.7.B.3)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**Advice** Engine oil leak

**MOT #10** 2014-09-06 09:06

**MOT test number** 365719744220

Result \( \sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Rear backplates damp

**MOT #9** 2013-09-09 12:26

MOT test number 746332253218

**Result** 
✓ Passed

**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)

MOT #8 2013-09-09 11:53

**MOT test number** 188192853290

Result × Failed

**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

**Advice** Nearside Front Road wheel slightly damaged (4.2.A.1a)

CarCheck.co.uk page 5/12



**MOT** test number

Result

R637AHJ

report date: 2024-03-29

873683718313

✓ Passed

MOT #7	2012-08-04 13:38
MOT test number	268247212219
Result	✓ Passed
MOT #6	2012-08-03 12:13
MOT test number	218196512241
Result	<b>×</b> Failed
Fail Nearside rear brake grabbing severely (3.7.A.5b)	
Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)	
MOT #5	2011-02-25 11:38
MOT test number	905196651022
Result	✓ Passed
MOT #4	2009-12-12 11:25
MOT test number	931316949353
Result	✓ Passed
MOT #3	2008-11-08 11:10

MOT #2	2007-05-03 17:01
MOT test number	500213027134
_	

MOT #1	2006-05-02 16:25
MOT test number	743312026112
Result	<b>✓</b> Passed

CarCheck.co.uk page 6/12



R637AHJ report date: 2024-03-29



**MOT** expiry date 1 November 2024

**Full MOT history** See MOT history

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

_	
Owner	hictory
OWITE	HIISLUH V

o met motory	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
********	
***************************************	
THE STREET STREET	
*********	
***************************************	
THE PROPERTY OF THE PROPERTY O	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	OK STEE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



R637AHJ report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1997-09-03
Last registration	2023-11-02
Complete history	See info



Registration #1	1997-09-03	10 mi
Registration #2	2006-05-02	48.339 mi
Registration #3	2007-05-03	51.045 mi
Registration #4	2008-11-08	55.016 mi
Registration #5	2009-12-12	56.807 mi
Registration #6	2011-02-25	59.527 mi
Registration #7	2012-08-03	61.905 mi
Registration #8	2012-08-04	61.905 mi
Registration #9	2013-09-09	63.763 mi
Registration #10	2013-09-09	63.763 mi
Registration #11	2014-09-06	65.309 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 11/12



R637AHJ report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1698 mm
Height	1393 mm
Length	4433 mm

## Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	08268715

CarCheck.co.uk page 12/12