





report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM X SPORT TDCI
Colour	Blue
Year of manufacture	2009
Top speed	139 mph
0 - 60 mph	8.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	57.7 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history


Entry 1

Date 2021-10-13

Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-27
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	28
Total items failed	10

MOT #18		2023-09-25 15:28
MOT test	number	747860764201
Result		✓ Passed
Next expi	ry date	2024-09-27
Advice	Exhaust mounting defective 2nd from rear (6.1.2 (a))	
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #17	20	22-09-28 13:40
MOT test	number	391182198147
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice Rear Sub-frame corroded but not seriously weakened Rear & Front (5.3.3 (b) (i))		
Advice	Nearside Front Tyre slightly damaged/cracking or perishing Small damage to outside	e (5.2.3 (d) (ii))
Advice Exhaust mounting defective Hanger bracket detached at front & center. Held on at backbox and flexi only. (6.1.2 (a))		

CarCheck.co.uk page 3/14



Advice

arm (5.3.4 (a) (i))

BV59ZCZ

report date: 2024-03-29

MOT #16 2022-09-24 12:00 628437579546 **MOT** test number Result **X** Failed **Advice** Nearside Front Tyre slightly damaged/cracking or perishing Small damage to outside (5.2.3 (d) (ii)) Fail Nearside Rear Suspension arm pin or bush excessively worn Trailing arm bush (5.3.4 (a) (i)) Advice Rear Sub-frame corroded but not seriously weakened Rear & Front (5.3.3 (b) (i)) Advice Exhaust mounting defective Hanger bracket detached at front & center. Held on at backbox and flexi only. (6.1.2 (a)) Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing

MOT #15	2021-09-28 08:09
MOT test number	673209143953
Result	√ Passed
MOT #14	2021-02-22 11:15
MOT test number	461892447993
Result	✓ Passed
MOT #13	2020-02-13 12:40
MOT test number	452008037317
Result	✓ Passed
MOT #12	2019-03-07 16:32

MOT #12		2019-03-07 16:32
MOT test	number	100360442510
Result		✓ Passed
Advice	Emissions 0.02	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Undertrays fitted	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 4/14



report date: 2024-03-29

✓ Passed

MOT #11 2018-07-26 12:13

MOT test number 268443957387

Result ✓ Passed

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Result

MOT #10 2017-07-11 12:11

MOT test number 745387448217

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #9 2017-07-11 08:34

MOT test number 309776112332

Result X Failed

Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Fail Front Tyre tread depth below requirements of 1.6mm both sides (4.1.E.1)

MOT #8 2016-08-01 15:29

MOT test number 588682351828

Advice Wipers

CarCheck.co.uk page 5/14



report date: 2024-03-29

2016-08-01 08:23 **MOT #7** 561965238021 **MOT** test number Result **★** Failed Fail Parking brake: efficiency below requirements (3.7.B.7) Front Brake pad(s) wearing thin (3.5.1g) Advice **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Offside Rear Brake lever has restricted free movement caliper (3.5.1k) Fail Parking brake lever has no reserve travel (3.1.6b) Advice Wipers **Advice** Rear Brake pad(s) wearing thin (3.5.1g) Fail Offside Brake cable has restricted free movement (3.5.1k) Fail Offside Rear brake caliper has restricted free movement (3.5.1k)


MOT #6	2015-07-31 11:54
MOT test number	808692915271
Result	✓ Passed
MOT #5	2014-09-30 11:03
MOT test number	796613074241
Result	✓ Passed
Advice Front registration plate deteriorated but	t not likely to be misread (6.3.1d)
Notice O/s front tyre worn on inner edge	

MOT #4	2013-09-30 10:55
MOT test number	997663873217
Result	✓ Passed
Notice Rear tyres wearing un evenly in tread	

CarCheck.co.uk page 6/14



report date: 2024-03-29



MOT #2	2012-10-01 12:16
MOT test number	365095872212
Result	✓ Passed
MOT #1	2012-10-01 12:16
MOT test number	105825172203
Result	★ Failed
Pass with rectification	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check

Tax expired: 5 March 2024



✓ MOT

Expires: 27 September 2024

Tax status	Expired at 5 March 2024
Days left	55 days too late
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



BV59ZCZ report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



More info >

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this FORD had different number plates. about of pliates faste since

CarCheck.co.uk page 11/14



BV59ZCZ report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-30
Last registration	2023-09-25
Complete history	See info



Registration #1	2009-09-30	11 mi
Registration #2	2012-10-01	42.990 mi
Registration #3	2013-09-30	59.571 mi
Registration #4	2014-09-30	74.905 mi
Registration #5	2015-07-31	84.977 mi
Registration #6	2016-08-01	97.485 mi
Registration #7	2016-08-01	97.485 mi
Registration #8	2017-07-11	107.838 mi
Registration #9	2017-07-11	107.839 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		11.777 mg

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Kerb weight	1570 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number 9U48397