





report date: 2024-03-28

#### General information

Make	FIAT
Model	DOBLO 8V ACTIVE
Colour	Blue
Year of manufacture	2008
Top speed	90 mph
0 - 60 mph	17.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.2 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



## Internet history

_	_	_		_	-
드	n	C	ľν	7	1

Life y 1	
Date	2021-09-20
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-08-13
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	31
Total items failed	0

MOT #15	2023-07-27 11:19
MOT test number	368466162369
Result	✓ Passed
Next expiry date	2024-08-13
Minor Headlamp lens slightly defective both (4.1.1 (b) (i))  Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))	

MOT #14	2022-08-03 08:17
MOT test number	832941899944
Result	<b>✓</b> Passed

Result	✓ Passed
MOT #13	2021-08-06 11:12
MOT test number	536450768785
Result	✓ Passed
Advice Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

CarCheck.co.uk page 3/13



MOT #12

MOT test number

Result

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2020-07-30 11:15 **MOT** test number 641783215654 Result **X** Failed **MAJOR** Nearside Front Service brake excessively fluctuating (1.2.1 (e)) **MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i)) **MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a)) Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice Rear axle modified for wheel chair use **MAJOR** Offside Front Service brake excessively fluctuating (1.2.1 (e)) **MAJOR** Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords both (5.2.3 (d) (i)) Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) **Advice MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #10	2019-04-17 11:31
MOT test number	590705866631
Result	<b>√</b> Passed

CarCheck.co.uk page 4/13



MOT #9

MOT test number

Result

Advice Fuel tank corroded

Advice Chip in windscreen

MOT #8

MOT test number

886136058128

Result

Advice Fuel tank corroded

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7

MOT test number

151557225261

Result

Advice Front tyres worn smooth on inner edges

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Exhaust deteriorated (non standard exhaust fitted)

Advice Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #6

MOT test number

866952413448

Result

Advice Oil leak

2015-10-27 10:35

CarCheck.co.uk page 5/13



MOT #5 2014-09-26 15:02 **MOT test number** 349829064461 Result ✓ Passed **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Nearside Macpherson strut has slight movement at the upper attachment (2.5.A.1c) Advice Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Oil leak Advice Offside Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #4		2013-10-21 16:11
MOT test i	number	526794993246
Result		✓ Passed
MOT #3		2012-10-17 15:05
MOT test i	number	146951492276
Result		✓ Passed
Notice	Front tyre are bald on the inside edges of tread offside front strong advise	

MOT #2	2011-11-22 14:01
MOT test number	416446821378
Result	✓ Passed
MOT #1	2011-01-11 12:22
MOT test number	537991711076
Result	✓ Passed

CarCheck.co.uk page 6/13





## Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	13 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-


CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
eneck it in the premium report and see an owner registrations. Download the fair report	<del>nere</del> .
***************************************	
***************************************	
***************************************	
***************************************	
*************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Correct registration	OK SIE
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-01-22
Last registration	2023-07-27
Complete history	See info



Registration #1	2008-01-22	26 mi
Registration #2	2011-01-11	20.604 mi
Registration #3	2011-11-22	27.159 mi
Registration #4	2012-10-17	35.387 mi
Registration #5	2013-10-21	39.606 mi
Registration #6	2014-09-26	51.385 mi
Registration #7	2015-10-27	59.272 mi
Registration #8	2016-11-08	69.072 mi
Registration #9	2017-10-10	76.640 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		0.00 44
Registration #17		9.777 no

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1722 mm
Height	2073 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg
Max. allowed weight	1830 kg

## Additional information

Fuel tank capacity	60 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 4336861