





### General information

Make	HONDA
Model	ACCORD I-DTEC EX GT
Colour	Black
Year of manufacture	2009
Top speed	129 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	Н







# Internet history

Entry	1
Date	

Pictures

2022-01-28

30

Listing price

View report









source: cargurus.co.uk



### MOT history

MOT expiry date	2024-08-27
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #14	2023-08-14 15:36	
MOT test number	995683234953	
Result	✓ Passed	
Next expiry date 2024-08-27		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))		
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))		

MOT #13	2023-08-14 13:42
MOT test number	132839856171
Result	🗙 Failed
Advice Exhaust heat shield loose	
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))	
Fail (b))Nearside Front Headlamp has a product on the lens so that the light output	t is severely reduced (4.1.4
Minor Nearside Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened both	h (1.1.14 (a) (ii))
FailOffside Front Headlamp has a product on the lens so that the light output i(b))	s severely reduced (4.1.4



Μ	F59DXW
	report date: 2024-03-28

MOT #12		2022-08-08 14:02
MOT test	number	232551684123
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11		2021-08-28 15:26
MOT test	number	550873862518
Result		✓ Passed
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #10	2020-03-10 13:16
MOT test number	868580208094
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #9	2020-03-10 13:16
MOT test number	627229080578
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectificationOffside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #8	2019-03-19 13:57
MOT test number	160194542462
Result	Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	





MOT #7	2018-03-21 15:33
MOT test number	335553832737
Result	✓ Passed
Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)	
MOT #6	2017-08-25 10:23
MOT test number	400508499135
Result	✓ Passed
MOT #5	2016-08-04 08:46
MOT test number	872506745835
Result	✓ Passed
MOT #4	2015-09-04 13:15
MOT test number	504898130372
Result	Passed
Advice Offside and nearside front tyres heavily cracking	
MOT #3	2014-08-13 15:21
MOT test number	377905324419
Result	✓ Passed
MOT #2	2013-08-20 16:32
MOT test number	526542533236
Result	✓ Passed
<b>Notice</b> Very slight age cracking on rear tyres	





MOT #1	2012-08-03 12:05
MOT test number	307296912236
Result	✓ Passed
AdviceNearside Rear Tyre worn close to the legal limit (4.1.E.1)AdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	



MF59DXW report date: 2024-03-28

# Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 April 2025	<b>Expires:</b> 27 August 2024
Tax status	Valid until 1 April
Days left	337
MOT expiry date	27 August 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Law P
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	 ₩.
Category	 AMPT
Туре	

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this HONDA had different number pla	tes.
Number of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-01
Last registration	2023-08-14
Complete history	See info



Registration #1	2009-09-01	18 mi
Registration #2	2012-08-03	51.845 mi
Registration #3	2013-08-20	69.664 mi
Registration #4	2014-08-13	79.705 mi
Registration #5	2015-09-04	96.238 mi
Registration #6	2016-08-04	109.362 mi
Registration #7	2017-08-25	125.571 mi
Registration #8	2018-03-21	128.093 mi
Registration #9		11.777 mi
Registration #10		
Registration #11		11,777 au
-		01,000 est
Registration #11		0.000 es
Registration #11 Registration #12		0.000 es
Registration #11 Registration #12 Registration #13		0.000 es





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1840 mm
Height	1440 mm
Length	4726 mm
Wheel base	2705 mm
Kerb weight	1593 kg
Additional information	
Fuel tank capacity	65 l
Fuel delivery	Direct Injection
	Direct injection
Number of doors	4
Number of doors Number of seats	-