





report date: 2024-03-28

General information

Make	MINI
Model	MINI ONE
Colour	Black
Year of manufacture	2012
Top speed	116 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	127 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history

Entry 1

Date 2021-06-19

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-01-02
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #11	2024-01-03 15:19
MOT test number	129824368274
Result	✓ Passed
Next expiry date	2025-01-02

MOT #10	2	024-01-03 14:30
MOT test	number	308526061601
Result		X Failed
MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)))

MOT #9	2022-12-07 14:23
MOT test number	547503534334
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2021-12-10 17:10
MOT test number	739334046184
Result	✓ Passed
Advice Rear Inner Brake pad(s) wearing thin About 2mm (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7

MOT test number

Result

Advice Front brake pads on limit

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Rear tyre starting to crack and deteriorate

MOT #4 2017-10-31 13:47 **MOT** test number 885669503747 Result ✓ Passed **MOT** #3 2016-12-14 14:17 **MOT** test number 924835239928 Result ✓ Passed Mud obscuring underside components **Advice Advice** Covers & trays fitted

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #2	2015-05-29 09:26
MOT test number	328239445109
Result	✓ Passed
MOT #1	2015-02-03 10:27
MOT test number	137614135469
Result	✓ Passed
Notice Items removed from driver's view prior to test	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	2 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



CE120FN report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO.	

	More info >
	, , ,
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



CE120FN report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-19
Last registration	2024-01-03
Complete history	See info



Registration #1	2012-03-19	29 mi
Registration #2	2015-02-03	16.440 mi
Registration #3	2015-05-29	17.508 mi
Registration #4	2016-12-14	22.707 mi
Registration #5	2017-10-31	24.231 mi
Registration #6	2018-10-31	28.241 mi
Registration #7	2019-10-30	30.580 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		0.777 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1060 kg
Max. allowed weight	1530 kg

Additional information

Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine numberA024J283