





report date: 2024-03-29

General information

| Make | RENAULT |
|---------------------|-----------------------|
| Model | KANGOO EXPRESSION 16V |
| Colour | Blue |
| Year of manufacture | 2012 |
| Top speed | 102 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 105 BHP |
|-------------------------|---------------------|
| Max. torque | 148 Nm at 3.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.1 mpg |
| Consumption extra urban | 43.5 mpg |
| Consumption combined | 36.7 mpg |
| CO2 emission | 180 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-30

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



BU12SFF report date: 2024-03-29

MOT history

| MOT expiry date | 2024-11-11 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 8 |
| Failed MOT tests | 4 |
| Total advice items | 11 |
| Total items failed | 7 |

| MOT #12 | | 2023-10-17 08:18 |
|-----------|--|------------------|
| MOT test | number | 577902176682 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-11-11 |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both (1. | 1.14 (a) (ii)) |
| Advice | Rear Tyre worn close to legal limit/worn on edge both on limits (5.2.3 (e)) | |
| Advice | Rear Passenger seat(s) missing at time of test all | |

| MOT #11 | | 2022-10-13 13:46 |
|----------|--|------------------|
| MOT test | number | 658524054032 |
| Result | | ✓ Passed |
| Advice | Rear Tyre worn close to legal limit/worn on edge both on limits (5.2.3 (e)) | |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice | Rear Passenger seat(s) missing at time of test all | |
| Advice | Central Brake pipe corroded, covered in grease or other material 2x front to rea | or (1.1.11 (c)) |

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #10 2022-10-12 13:09

MOT test number 141133552335

Result X Failed

Advice Central Brake pipe corroded, covered in grease or other material 2x front to rear (1.1.11 (c))

Advice Rear Tyre worn close to legal limit/worn on edge both on limits (5.2.3 (e))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

Advice Rear Passenger seat(s) missing at time of test all

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #9 2021-11-12 16:24

MOT test number 982592502965

Result ✓ Passed

MOT #8 2021-11-10 15:23

MOT test number 407863538383

Result ★ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #7 2019-01-30 14:26

MOT test number 612429833442

Result

Passed

MOT #6 2019-01-30 14:26

MOT test number 242519241938

Result X Failed

Pass with rectification Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

| MOT # | 5 | 2018-04-10 12:01 |
|--------|--|------------------|
| MOT to | est number | 816616029597 |
| Result | | ✓ Passed |
| | | |
| MOT # | 4 | 2018-04-09 13:48 |
| MOT to | est number | 955786593988 |
| Result | | × Failed |
| Fail | Front Windscreen wiper does not clear the windscreen effectively n/s and o/s (8.2.2) |) |
| Fail | Rear Brake pad(s) has restricted free movement N/S and O/S (3.5.1k) | |
| Fail | Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c |) |

| | , |
|-----------------|------------------|
| | |
| MOT #3 | 2017-04-11 13:58 |
| MOT test number | 426214522040 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2016-05-05 10:11 |
| MOT test number | 877665020902 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2015-05-18 12:26 |
| MOT test number | 808028335171 |
| Result | ✓ Passed |
| | |

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 185 |
| MOT expiry date | 11 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. about of pliates faste since

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12




report date: 2024-03-29

Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2012-05-18 |
| Last registration | 2023-10-17 |
| Complete history | See info |



| Registration #1 | 2012-05-18 | 7 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-05-18 | 10.387 mi |
| Registration #3 | 2016-05-05 | 11.950 mi |
| Registration #4 | 2017-04-11 | 14.891 mi |
| Registration #5 | 2018-04-09 | 17.522 mi |
| Registration #6 | 2018-04-10 | 17.578 mi |
| Registration #7 | 2019-01-30 | 19.480 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.177 es |
| Registration #12 | | 11.777 44 |
| Registration #13 | | 11.177 mi |
| | | |

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 2133 mm |
|---------------------|---------|
| Height | 1898 mm |
| Length | 4213 mm |
| Wheel base | 2697 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1924 kg |

Additional information

| Fuel tank capacity | 60 I | |
|-----------------------------------|-----------------------|------------|
| Fuel delivery | Multi-Point Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 2 | page 12/12 |

Number of axles 2

Engine number D013935