





report date: 2024-03-28

## General information

Make	BMW
Model	X6 XDRIVE35D
Colour	Blue
Year of manufacture	2008
Top speed	147 mph
0 - 60 mph	6.9 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	286 BHP
Max. torque	580 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	39.8 mpg
<b>Consumption combined</b>	34.0 mpg
CO2 emission	220 g/km
CO2 label	K



CarCheck.co.uk page 1/13



## Internet history

## Entry 3

Date 2021-11-05

Pictures 49

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

Date	2021-11-04
------	------------

Pictures 49

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1


Date	2021-06-05
Date	2021-00-03

Pictures 56

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



# MOT history

MOT expiry date	2025-01-25
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	17
Total items failed	5

MOT #17	2024-01-26 15:56
MOT test number	785711334410
Result	✓ Passed
Next expiry date	2025-01-25

MOT #16		2023-01-09 17:03
MOT test	number	291696913518
Result		✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Minor	Brake hose slightly twisted both front (1.1.12 (b) (i))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.	14 (a) (ii))
Minor to brake p	Electrical wiring inadequately secured nearside front brake pad wear sensor in pad (4.11 (a) (i))	nsecure not attached

CarCheck.co.uk page 3/13



**MOT #15** 2023-01-09 15:56

**MOT test number** 959304058355

Result X Failed

Advice Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

**Minor** Electrical wiring inadequately secured nearside front brake pad wear sensor insecure not attached to brake pad (4.11 (a) (i))

Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Minor** Brake hose slightly twisted both front (1.1.12 (b) (i))

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

**MOT #14** 2021-12-17 16:12

MOT test number 123322562198

**Result** ✓ Passed

MOT #13 2021-08-05 15:08

MOT test number 690567645581

Result \( \sqrt{Passed} \)

**Advice** Under trays fitted under vehicle unable to see some components

**MOT #12** 2020-12-12 17:01

MOT test number 932067568101

Result 

Passed

**Advice** Rear Service brake grabbing slightly (1.2.1 (c))

**Advice** Under tray fitted.

CarCheck.co.uk page 4/13



MOT #11

MOT test number

267507449538

Result

Advice Under tray fitted.

Minor Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10

MOT test number

881184361929

Result

Advice Under tray fitted.

MOT #9

MOT test number

Result

Advice Under trays fitted underneath.

Advice Items removed from driver's view prior to test

MOT #8

MOT test number

279288320357

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

 MOT #7
 2016-02-23 14:34

 MOT test number
 172453138855

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



MOT #6		2016-02-23 14:34
MOT test number		463656169563
Result		<b>x</b> Failed
Pass with rectification	Front registration plate insecure (6.3.1b)	

Pass with rectification	Front registration plate insecure (6.3.1b)	
MOT #5		2015-02-27 14:37
MOT test number		729548955015
Result		✓ Passed
MOT #4		2014-02-17 16:21
MOT test number		987368944042
Result		<b>✓</b> Passed
MOT #3		2013-09-19 09:05
MOT test number		147962063204
Result		<b>✓</b> Passed
MOT #2		2012-09-10 10:22
MOT test number		477584152252
Result		✓ Passed
MOT #1		2011-09-13 12:44
MOT test number		598456051212
Result		✓ Passed

CarCheck.co.uk	page 6/13





# Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	25 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



## Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



## Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



# Owner history

For how long did the current and previous owner(s) have this BMW? How many owners defined the premium report and see all owner registrations. Download the full report is	
HARMAN CO.	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



## Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-29
Last registration	2024-01-26
Complete history	See info



Registration #1	2008-09-29	27 mi
Registration #2	2011-09-13	22.740 mi
Registration #3	2012-09-10	29.682 mi
Registration #4	2013-09-19	34.111 mi
Registration #5	2014-02-17	34.640 mi
Registration #6	2015-02-27	39.455 mi
Registration #7	2016-02-23	44.527 mi
Registration #8	2016-02-23	44.527 mi
Registration #9	2016-10-19	47.649 mi
Registration #10	2017-11-24	54.071 mi
Registration #11	2018-11-24	59.014 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		11.337 mi

More info >

CarCheck.co.uk page 12/13



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1983 mm
Height	1690 mm
Length	4877 mm
Wheel base	2933 mm
Kerb weight	2185 kg
Max. allowed weight	2710 kg

# Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 13/