





report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 ACTIVE
Colour	Blue
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	73 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	44.8 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-15
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	9
Total items failed	10

MOT #14	2023-10-30 09:54
MOT test number	100014005935
Result	✓ Passed
Next expiry date	2024-11-15

MOT #13	2022-11-15 17:10
MOT test number	139544870887
Result	✓ Passed

MOT #12		2022-11-15 17:10
MOT test number		917107262461
Result		× Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #11	2021-11-16 15:25
MOT test number	413638007334
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #10 2021-11-02 17:16 **MOT** test number 594227333181 Result **X** Failed Fail Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail **Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT test number

Result

Advice Offside steering rack gaiter twisted

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside steering rack gaiter twisted.

MOT #8

MOT test number

726241057732

Result

Advice Oil leak

2019-01-16 09:57

726241057732

MOT test number

Result

Fail Electronic power steering warning lamp indicates a system malfunction (2.6 (a))

Advice Oil leak

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #6 2017-12-07 14:07 **MOT test number** 861311279503 Result ✓ Passed MOT #5 2017-12-07 09:10 **MOT test number** 474122298658 Result × Failed **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Electronic power steering warning lamp indicates a failure in the system (2.3.8) Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #4	2016-12-06 12:17
MOT test number	223288700882
Result	✓ Passed
MOT #3	2015-10-23 10:32
MOT test number	349871913252
Result	✓ Passed
Advice Rear Exhaust Mount Broken	

MOT #2		2014-10-24 16:43
MOT test number		557387594296
Result		✓ Passed
MOT #1		2014-10-24 16:43
MOT test number		877817094276
Result		X Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
Owner	HISLULY

Owner matery	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	IIK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-23
Last registration	2023-10-30
Complete history	See info



Registration #1	2011-09-23	9 mi
Registration #2	2014-10-24	32.197 mi
Registration #3	2015-10-23	40.194 mi
Registration #4	2016-12-06	48.177 mi
Registration #5	2017-12-07	54.280 mi
Registration #6	2017-12-07	54.280 mi
Registration #7	2019-01-07	58.025 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1229 kg
Max. allowed weight	1601 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number FSX46458693