





report date: 2024-03-28

# General information

Make	CITROEN
Model	DS5 E-HDI AIRDREAM DSTYLE EGS
Colour	Grey
Year of manufacture	2015
Top speed	119 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



# Internet history


### Entry 1

Date 2021-09-09


Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOTHIStory	
MOT expiry date	2024-10-13
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	0
	****
MOT #7	2023-10-10 15:55
MOT test number	220228373751
Result	✓ Passed
Next expiry date	2024-10-13
MOT #6	2022-09-20 13:10
MOT test number	750000366210
Result	<b>✓</b> Passed
MOT #5	2021-10-12 10:40
MOT test number	931533197610
Result	<b>✓</b> Passed
MOT #4	2020-09-25 10:37
MOT test number	811075148007
Result	✓ Passed

CarCheck.co.uk page 3/11



Result

PK65LCT report date: 2024-03-28

Passed

MOT #3 2020-09-24 12:24

MOT test number 266864605285

**Result** X Failed

MAJOR Nearside Front Side repeater light intensity significantly reduced (4.4.3 (a))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2019-09-26 11:43

**MOT test number** 179917418469

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #1** 2018-10-06 09:52

**MOT test number** 227420283750

**Result** ✓ Passed

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	13 October 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



PK65LCT

report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



PK65LCT

report date: 2024-03-28

Owner	I-!
OWNER	nistory
	11136017

*		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		OEN
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK C	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-10-14
Last registration	2023-10-10
Complete history	See info



Registration #1	2015-10-14	24 mi
Registration #2	2018-10-06	22.050 mi
Registration #3	2019-09-26	29.155 mi
Registration #4	2020-09-24	35.954 mi
Registration #5	2020-09-25	35.954 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



# Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm

# Additional information

Number of axles	2
Engine number	JBFT0091772

CarCheck.co.uk page 11/11