



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI COMFORT
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	12.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	113 BHP
Max. torque	253 Nm at 2.500 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	150 g/km
CO2 label	F





MOT history

MOT expiry date	2024-10-11
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #13	2023-10-12 14:36
MOT test number	205067263809
Result	✓ Passed
Next expiry date	2024-10-11

MOT #12	2022-03-14 09:52
MOT test number	339477847952
Result	✓ Passed

MOT #11	2021-03-15 10:48
MOT test number	161397169041
Result	✓ Passed

MOT #10	2020-06-08 10:03
MOT test number	681120861054
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #9	2020-06-08 10:03
MOT test number	127886516512
Result	✗ Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #8	2019-06-21 11:55
MOT test number	222640336941
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	All tyres cracking due to age
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2018-06-23 11:36
MOT test number	111194044449
Result	✓ Passed
Advice	Fuel tank filler pipes corroded

MOT #6	2017-06-03 09:27
MOT test number	312590162465
Result	✓ Passed
Advice	Fuel filler pipes corroded

MOT #5	2016-06-29 14:09
MOT test number	639892717493
Result	✓ Passed
Advice	Nearside Front Valve stem slightly damaged (4.1.D.1e)
Advice	Nearside Rear Valve stem slightly damaged (4.1.D.1e)

**MOT #4** 2015-08-13 12:06**MOT test number** 817015425265**Result** ✓ Passed**MOT #3** 2015-08-13 12:06**MOT test number** 346165225428**Result** ✗ Failed**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**MOT #2** 2015-01-28 14:49**MOT test number** 275898625033**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2014-01-21 12:59**MOT test number** 165541424475**Result** ✓ Passed**Notice** N/s/r tyre starting to crack**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
11 October 2024

Tax status		Valid until 1 September
Days left		126
MOT expiry date		11 October 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2023-03-28
Current registration	 XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-01-31
Last registration	2023-10-12
Complete history	See info



Registration #1	2011-01-31	15 mi
Registration #2	2014-01-21	29.926 mi
Registration #3	2015-01-28	39.359 mi
Registration #4	2015-08-13	41.732 mi
Registration #5	2016-06-29	43.350 mi
Registration #6	2017-06-03	46.943 mi
Registration #7	2018-06-23	56.824 mi
Registration #8	2019-06-23	56.824 mi
Registration #9	2020-06-23	56.824 mi
Registration #10	2021-06-23	56.824 mi
Registration #11	2022-06-23	56.824 mi
Registration #12	2023-06-23	56.824 mi
Registration #13	2024-06-23	56.824 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1490 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1403 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBBZ334761