



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Black
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg



LABEL UNKNOWN



MOT history

MOT #13	2020-09-14 14:13
MOT test number	375105353798
Result	✓ Passed
Next expiry date	2021-09-19
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #12	2020-09-11 10:26
MOT test number	833757669316
Result	✗ Failed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11	2019-09-20 11:43
MOT test number	855236824652
Result	✓ Passed
Advice	Nearside Rear brake slightly binding

**MOT #10** 2018-09-18 10:54**MOT test number** 116620575245**Result** ✓ Passed**MOT #9** 2018-09-15 08:52**MOT test number** 524057941984**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #8** 2017-09-18 12:38**MOT test number** 580643228286**Result** ✓ Passed**MOT #7** 2016-08-23 09:01**MOT test number** 780710490648**Result** ✓ Passed**Advice** Engine oil low

**MOT #6** 2016-08-23 09:00**MOT test number** 881955858272**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Engine oil low**MOT #5** 2015-09-12 09:25**MOT test number** 804373456228**Result** ✓ Passed**MOT #4** 2014-09-06 11:15**MOT test number** 488739044278**Result** ✓ Passed**MOT #3** 2013-08-14 13:10**MOT test number** 388816623229**Result** ✓ Passed**MOT #2** 2012-08-30 14:53**MOT test number** 136803142219**Result** ✓ Passed**MOT #1** 2012-08-30 13:31**MOT test number** 909413742203**Result** ✗ Failed**Fail** Brake hose leaking (3.6.A.1)**Advice** Nearside Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-09-11
Last registration	2020-09-14
Complete history	See info



Registration #1	2009-09-11	28 mi
Registration #2	2012-08-30	24.687 mi
Registration #3	2012-08-30	24.687 mi
Registration #4	2013-08-14	30.719 mi
Registration #5	2014-09-06	46.891 mi
Registration #6	2015-09-12	64.400 mi
Registration #7	2016-08-23	86.240 mi
Registration #8	2019-09-14	95.277 mi
Registration #9	2019-09-14	95.277 mi
Registration #10	2019-09-14	95.277 mi
Registration #11	2019-09-14	95.277 mi
Registration #12	2019-09-14	95.277 mi
Registration #13	2019-09-14	95.277 mi
Registration #14	2019-09-14	95.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462