



report date: 2024-03-28

General information

Make	MINI
Model	ONE CLUBMAN
Colour	Silver
Year of manufacture	2011
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	153 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-22
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #13	2023-10-06 10:58
MOT test number	432544148522
Result	✓ Passed
Next expiry date	2024-10-05

MOT #12	2022-09-23 09:17
MOT test number	114028437145
Result	✓ Passed

MOT #11	2022-09-16 10:09
MOT test number	769164916506
Result	✗ Failed

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits co at 0.9% after 2nd fast idle (8.2.1.2 (a))

**MOT #10** 2021-09-08 08:06**MOT test number** 365154892520**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-09-21 11:00**MOT test number** 676145932687**Result** ✓ Passed**MOT #8** 2019-06-11 11:32**MOT test number** 157640012125**Result** ✓ Passed**Advice** Oil leak**MOT #7** 2018-06-01 10:05**MOT test number** 750295882022**Result** ✓ Passed**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**MOT #6** 2017-06-13 13:33**MOT test number** 700807952527**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #5** 2016-06-08 14:07**MOT test number** 998846645717**Result** ✓ Passed**MOT #4** 2015-06-11 16:03**MOT test number** 998912365136**Result** ✓ Passed**MOT #3** 2015-04-16 12:35**MOT test number** 255106905128**Result** ✓ Passed

- Notice** Side walls perished on all four tyres
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2015-04-16 12:35**MOT test number** 606206805164**Result** ✗ Failed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Side walls perished on all four tyres
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2014-03-31 10:02
MOT test number	255370894032
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	VO11YKU
Plate since	2019-09-29
Current registration	VO11YKU
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-04-08
Last registration	2023-10-06
Complete history	See info



Registration #1	2011-04-08	12 mi
Registration #2	2014-03-31	16.262 mi
Registration #3	2015-04-16	21.142 mi
Registration #4	2015-06-11	21.376 mi
Registration #5	2016-06-08	31.788 mi
Registration #6	2017-06-13	41.523 mi
Registration #7	2018-06-01	57.051 mi
Registration #8	2019-06-01	72.579 mi
Registration #9	2020-06-01	88.107 mi
Registration #10	2021-06-01	103.635 mi
Registration #11	2022-06-01	119.163 mi
Registration #12	2023-06-01	134.691 mi
Registration #13	2024-06-01	150.219 mi
Registration #14	2025-06-01	165.747 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1426 mm
Length	3937 mm
Wheel base	2547 mm
Kerb weight	1140 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	B256I998